



# STOP SALE

Release Date: November XX, 2022

# IND

Communication #: I-22-06

Model Year(s): 2021-2022

— Confidential and Proprietary —

**VERSION: R01 (November XX, 2022)**

## **IMPORTANT STOP SALE NOTICE!** **Stop selling and riding affected vehicles immediately.**

### **SUBJECT: FUEL PUMP**

### **PURPOSE**

Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

Indian Motorcycle is currently evaluating a repair procedure for this concern and will provide an update to dealers in the coming weeks.

### **AFFECTED MODELS**

MODEL YEAR	MODELS	AFFECTED RANGE
2021-2022	Scout	Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.
2022	Chief	

### **CUSTOMER NOTIFICATION**

When repair details are available, Indian Motorcycle will notify consumers by letter (and email if available) immediately and follow-up with additional repair plans. At that time, dealers should also contact owners of affected VINs / PINs to inform them of this announcement.

### **CONTACT POLARIS**

If you have questions that are not addressed in this document, contact Indian Motorcycle Service through Ask Polaris or by phone at 800-330-9407 (US/Canada Dealers Only).

### **DEALER - WHAT TO DO?**

As of November XX, 2022, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED Model Year 2021-2022 Scout or 2022 Chief models** affected by this **Stop Sale** until it is repaired according to the **Safety Recall**.