



Service Memo



Technical

Miller Electric Mfg. LLC

An Illinois Tool Works Company
1635 West Spencer Street
Appleton, WI 54912 USA
920-735-4505 or
Toll Free: 866-931-9733

Forward to: Service Administration
From: Power Systems Division
Date: March 1, 2022
Number: 1286
Subject: EnPak A60 Wires Rubbing on Main Drive Belt

Model	Stock Number	Serial Number Range
EnPak A60GB	907813, 907813001	Prior to Serial No. NC080172R
EnPak A60GBH	907814, 907814001	
EnPak A60GBHW	907815, 907815001	

Inspect Enpak A60s to ensure the battery cables and ground wire that travel under the drive belt are not compromised by contacting the belt. Secure cables as shown below. We are also adding a revised bracket to shield the belt from the hydraulic, compressor, and fuel lines.



To correct this issue, install kit 291818 and closely follow the instructions.

Please contact the Power Systems Division Service Group at 920-735-4505 or psdservice@millerwelds.com if you have any questions.

Normal warranty procedures apply. A maximum of 1.5 hours will be allowed for this repair.

