



Campaign code:
L62X-R.02.22

Campaign name:
Insufficient Gearbox Oil

Model:
Huracàn STO, Huracàn EVO

Model Year:
MY20, MY22

Limited or special editions:
All version

Markets:
China, Germany, Hong Kong, Japan, New Zealand, Switzerland, Thailand, UK, USA

VIN Identification:
From 15247 to 19058


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the "VIN Info" function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific procedure, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



N.B.:

Procedure A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. it has been determined that the subject vehicles gearbox oil quantity may be too low due to a supplier mistake.

Solution for the field:

Replacing the gearbox oil

Spare Parts:

No spare parts required

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation B: 1 h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the "LIASS" system on the Lamborghini portal and, following the instructions in the system's "Manuals" section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Header

CC: [Dropdown menu]

Problem: A-Test 1, B-Test 2, C-Test 3

Cost Code: 50 Service Campaign

Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPTION B: Replacing the gearbox oil**
 - o Labour time: 1 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section "Service and Recall Campaigns":

Automobili Lamborghini S.p.A.
 Campagne service assistenza e campagne di richiamo / Service- und Rückrufaktion / Service and Recall Campaign
 Servicio de campañas de rappel / Campaña de Servicio y Llamada a Taller

[Form with multiple sections for service and recall campaigns, including checkboxes for service type, date, and location, and fields for technician and customer information.]

Tools/Materials required

Code	Description.	Qty.
G 052 529 A2	Gearbox oil	10.5 L (2.77 U.S. gal)
ASE 401 346 01 000	Gearbox oil filler tool - VAS 6262A	1
ASE 409 103 00 000	Gearbox oil filler adapter - VAS 6262/6	1



N.B. (*)

All ODIS technical documentation can be viewed on the Lamborghini web portal, in the ODIS section.



Repair method:

Replace the gearbox oil following the instructions contained in the Workshop Manual at the path:

03 Transmission → 00 Automatic gearbox → Automatic transmission → Emptying/Filling/Bleeding



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or write to Technical Support (service.department@lamborghini.com).