







# **Flex Tech Quick Disconnect**

<b>Bulletin Type:</b>	Recall	<b>Publication Date:</b>	May 2022
Bulletin #(s):	22V-301, 2022-236	Make(s):	Jayco
Job Code(s):	9901577	Model(s):	North Point, Pinnacle,
-1	9901577A .10 Inspection Only	Model Year(s):	Seismic
Flat Rate(s):	9901577B .30 Replacement		2021-2022

Incident:	Porosity and contamination of the brass on the Quick Disconnect.
Affected Units:	Certain 2021-2022 Jayco North Point, Pinnacle; Certain 2022 Jayco Seismic
Parts Kit:	Kit#: 22V-301A
	Contents: 1 ea Quick Disconnect
Misc. Tools & Supplies:	Soapy Water spray, Wrench

## **Flex Tech Quick Disconnect**

<b>Bulletin Type:</b>	Recall	<b>Publication Date:</b>	May 2022
7,000		Make(s):	Highland Ridge
Bulletin #(s):	22V-303, 2022-235		Mesa Ridge, Open
Job Code(s):	9904577	Model(s):	Range, Range Lite, Open Range Roamer
Flat Rate(s):  9904577A .10 Inspection Only 9904577B .30 Replacement	9904577A .10 Inspection Only		Range Lite, Silverstar
	· · · · · · · · · · · · · · · · · · ·	Model Year(s):	2021-2022

Incident:	Porosity and contamination of the brass on the Quick Disconnect.
Affected Units:	Certain 2021-2022 Highland Ridge Mesa Ridge, Open Range, Open Range Roamer Range Lite, Range Lite; Certain 2021-2022 Highland Ridge Silverstar
Doute Vit Dotoile	Kit#: 22V-301A
Parts Kit Details:	Contents: 1 ea Quick Disconnect
Misc. Tools & Supplies:	Soapy Water spray, Wrench










### **Flex Tech Quick Disconnect**

<b>Bulletin Type:</b>	Recall	Publication Date:	May 2022
Bulletin #(s):	22V-302, 2022-234	Make(s):	Starcraft
Job Code(s):	9902577	Model(s):	Super Lite Maxx, Super Lite
Flat Rate(s):	9902577A .10 Inspection Only 9902577B .30 Replacement	Model Year(s):	2022

Incident:	Porosity and contamination of the brass on the Quick Disconnect.
Affected Units:	Certain 2022 Starcraft Super Lite Maxx & Super Lite
Parts Kit Details:	Kit#: 22V-301A
	Contents: 1 ea. – Quick Disconnect
Misc. Tools & Supplies:	Soapy Water spray, Wrench

#### FLEX TECH QUICK DISCONNECT INSPECTION

 Inspect the Quick Disconnect at the exterior grill for a black dust cap. (Figure 1) File for inspection only if the dust cap is any other color. Complete repair instructions below if the dust cap is black.



#### INSTRUCTIONS FOR REPLACING THE FLEX TECH QUICK DISCONNECT

1) Replace the Quick Disconnect at the exterior grill location and use soapy water to check if there is an LP leak after installing the new Quick Disconnect.

Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540