


RECALL 22V395, 2022-289 REMEDY INSTRUCTIONS

	Make(s): ALTA & PALOMINO TRAILER Model(s): SEE BELOW Model Year(s): 2022	Repair Code: RC-090-01-00-004202 Allotted Time: .30 HRS. Inspection Code: N/A Allotted Time: N/A
	Concern: Per the component suppliers recall, 22E042: "The table could potentially drop down in the upright or closed position."	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: See Below Part(s) Return: NO, DESTROY

Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

East to West Part Number F100229728

Palomino Part Number F100185477

CERTAIN MODELS – 2022 – ALTA TRAILER – ALT2350KRK
2022 – PALOMINO TRAILER - PAT208SS & PAT242RBS

STEP 1: LOCATE THE TABLE;

STEP 2: LOWER TO THE "STOW" POSITION;

STEP 3: PICK TABLE UP BY HOLDING ONTO THE BLACK MECHANISM AND THE TABLE TOP;

STEP 4: PLACE TABLE TOP SIDE DOWN ONTO THE BED MATTRESS;

STEP 5: REMOVE ALL FASTENERS THAT ATTACH THE MECHANISM TO THE TABLE TOP THEN SET ASIDE;

STEP 6: REMOVE THE BLACK MECHANISM FROM THE TABLE AND DISCARD APPROPRIATELY;

STEP 7: PLACE THE REPLACEMENT MECHANISM ONTO THE TABLES' BOTTOM SIDE (SAME SIDE AS PRIOR MECHANISM)

STEP 8: USE FASTENERS FROM PRIOR MECHANISM TO SECURE THE NEW MECHANISM TO THE TABLES' BOTTOM (DO NOT STRIP OUT THE SCREWS);

STEP 9: ENSURE THE MECHANISM IS SECURED IN THE DOWNWARD POSITION AND THEN HOLD THE BOTTOM OF THE MECHANISM WITH ONE HAND AND TABLE TOP WITH THE OTHER AND FLIP OVER, SETTING ON THE FLOOR;

STEP 10: REDEPLOY TABLE TO UP-RIGHT POSITION, CHECK FOR PROPER FUNCTIONALITY;

STEP 11: CLEAN WORK AREA AND ANY DUST;

STEP 12: CLAIM REPAIR CODE.

NOTE: PHOTOS FOR REFERENCE.

RECALL 22V395, 2022-289 REMEDY INSTRUCTIONS



Make(s): ALTA & PALOMINO TRAILER
Model(s): SEE BELOW
Model Year(s): 2022

Concern:
Per the component suppliers recall, 22E042:
"The table could potentially drop down in the upright or closed position."

Repair Code: RC-090-01-00-004202
Allotted Time: .30 HRS.
Inspection Code: N/A
Allotted Time: N/A

Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: See Below
Part(s) Return: NO, DESTROY

