

Recall Bulletin 221104REV



RECALL BULLETIN:
221104REV

YEAR(S) AFFECTED:
2022-2023

PRODUCT(S) AFFECTED:

MY 2022-2023

Fleetwood
Bounder
Fortis
Southwind

Holiday Rambler:
Invicta
Vacationer

MODEL(S) AFFECTED:
All

SUBJECT:

Securing the Interior Step Tread to the plywood substrate

KEYWORDS:

Entry step, step tread

Issued:
December 2022

© 2022 REV Recreation Group, Inc.


The purpose of this Recall Service Bulletin is to inform REV Recreation Group dealers of the need to inspect, and if necessary, secure the interior step tread to the plywood substrate on certain model year 2022-2023 Fleetwood brand Bounder, Fortis and Southwind, Holiday Rambler brand Invicta and Vacationer, Class A Gas motorhomes. A list of affected motorhome serial numbers appears at the end of this Bulletin.

CONDITION:

On motorhomes affected by this recall campaign, the stationary manufactured step tread on interior entry steps, may have not been secured to the plywood substrate, causing potential for the tread to become loose, and may detach with step usage.

If a step tread detaches from its plywood substrate, the step tread may become unstable, shift, or detach posing a risk of personal injury.

Note: Read this entire Bulletin before proceeding.



[REDACTED]


before beginning any work. Prior authorization is required to be submitted.

Failure to follow these instructions could result in a [REDACTED]

REV RV Dealer Technical Support: (800) 816-9825

READ THIS ENTIRE BULLETIN CAREFULLY BEFORE PROCEEDING AND FOLLOW ALL SAFETY PRECAUTIONS.

Take a copy of this bulletin with you when servicing the unit.



TWO PHOTOS WILL BE REQUIRED, ONE OF EACH RECESSED HOLE IN THE STEP TREAD AFTER THE SCREWS ARE REMOVED. PHOTOS WILL BE REQUIRED IF THE STEP TREAD IS DAMAGED AND REQUIRES REPLACEMENT WHEN SUBMITTING FOR AUTHORIZATION.

NOTE: If you have questions or something is discovered that is not clearly defined in this bulletin, please contact REV RV DEALER TECHNICAL SUPPORT AT (800) 816-9825

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal law (section 154 of the national traffic and motor vehicle safety act of 1966) requires that: If you have received a notice of recall or failure to comply from REV Recreation Group or any component Manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

CORRECTION PROCEDURE:

1. Park the motorhome on a dry, level, paved hard surface. Place the transmission into Park. Engage the parking brake.
2. Turn off ignition and remove the keys. Maintain control of keys until all repairs are performed.
3. Chock the wheels to prevent movement.
4. Be cautious of pinch points on and near the mechanical entry step as it could move unexpectedly.

THINK SAFETY AND USE APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT TO AVOID INJURY.

CAUTION: ENTRY STEP MAY COME OUT WHEN OPENING THE ENTRY DOOR.

5. Open the entry door to access interior step treads.
6. Using a putty knife, carefully wedge it between the bottom step and the threshold. Carefully pry upwards to ensure the step tread is tightly secured. Be sure not to damage the tread surface. (See Figure 1) If the tread is loose, carefully clean dust and debris from in between the tread and the sheet metal. Remove any adhesive that may be between the step tread and the sheet metal with a putty knife. Apply a sufficient amount of **Loctite Power Grab** (purchased locally at box store) adhesive to the sheet metal in a random pattern for complete coverage. **Do not substitute!** Carefully reinstall the step tread, making sure to have the tread tight against the threshold. **Loctite Power Grab requires 24 hours to fully cure.**




Figure 1

7. Move to the center step. Using a putty knife, **carefully** remove nylon caps covering the top step tread fasteners. (See figure 2) Be sure not to damage the tread surface.



Figure 2



TWO (2) PHOTOS ARE REQUIRED, ONE OF EACH HOLE

8. Using a coin slotted bit remove the mounting screw and washer holding the tread in place. Inspect the step tread for damage/cracks at the recessed area where the screws were removed. Take a photo of each hole during your inspection. These photos will be needed for the claim. NOTE: Keep fasteners to be reused later. (See figure 3)



Figure 3



9. Once the screws are removed lift up and remove the step tread. Using a putty knife, **inspect** to see if tread is securely bonded to the plywood substrate. (See figure 4)
- A) If adhesive/sealant was used to bond the tread to the plywood substrate, carefully reinstall the step tread, screw/washer, and the nylon caps. Double check to ensure no damage was created at the screw holes (make sure to take photos of the holes prior to re-assembly, these will need to be submitted for authorization). No further action is required. NOTE: Do not over tighten or strip screws (Use hand tools). **Use Flat Rate Code 6308-11 Inspected/Not Defective**
- B) If the step tread is not bonded and can be pried apart from the plywood substrate using a putty knife, continue on to the next steps. **NOTE: This is most likely the scenario.**



Figure 4

10. Carefully clean all dust and debris from in between both the plywood substrate and step tread.

11. Apply a sufficient amount of **Loctite Power Grab** (purchased locally at box store) adhesive to the plywood substrate in a random pattern for complete coverage. **Do not substitute!!** (See figure 5 for proper application)



Figure 5

12. Flip the plywood substrate over and align the screw holes with the step tread. Firmly push plywood substrate into the step tread. Add quick grip clamps to prevent movement. (Make sure not to damage the tread surface). While still aligned, add a 1" pin nail to all four corners and at least 2 in the middle of the step tread to prevent movement while the adhesive cures. Clean up any adhesive oozing out between the two pieces. (See figure 6)



Figure 6

13. Carefully reinstall the step tread using the screw/washer, and nylon caps. Do not over tighten. (Use hand tools) (See figure 7)



Figure 7

Note: In the event the step tread mounting screws will not fully seat to hold the step tread in place, or are at risk of becoming stripped, the Parts kit will contain 2 clips and 4 screws for replacement on the sheet metal entry step frame. See instructions below to access the clips.



14. To gain access to the lower mounting clips, the step tread needs to be removed as well as the riser panel, and the sheet metal battery cover on the center step.

15. To remove the riser panel, locate and remove all four screws. (See figure 8)




Figure 8

16. Once the riser panel is removed, you can lift off the sheet metal battery cover. **Caution: Edges may be sharp. Please use cut resistant gloves.** (See figure 9)



Figure 9

Note: The batteries do not have to be removed to complete repairs; however, cover the battery terminals prior to beginning work and use insulated tools and personal protective equipment (e.g., gloves) to prevent accidental contact with battery terminals or wiring

17. Once the sheet metal battery cover is removed, you can see where the clip and screws are mounted to the step frame. Carefully remove the screws from the top making sure not to drop the screws in the battery compartment. Hold the clip from the underside with vice grips, making sure not to drop into the battery compartment. (See figure 10)



Figure 10



Figure 11

18. Line the new clip up with the center hole on the underside of the step frame and clamp it in place using vice grips. Install the new screws from the top side of the step frame.

Note: Below are examples of the clip mounting that you might find. The pre punched holes in the sheet metal may not be used. Key point is to ensure the center clip hole aligns with the sheet metal hole.



19. Once the new clips and screws are in place, reinstall the sheet metal battery cover, and riser panel. Carefully reinstall the step tread using the screw/washer. Be sure not over tighten the screws (Use hand tools) and re-insert the nylon caps. (See figure 7)

TOOLS:

Wheel chocks
Putty knife
Caulk Gun
Disposable Nitrile Gloves
Driver with bits

Cut Resistant Gloves
Utility Knife
Nail Gun
Quick Grip Clamps
Vice Grips

Coin Slotted Bit
Screwdriver



Example of Coin Slotted Bit

Step Tread Recall Kit

Qty: 1 ea. Part Number:10875229

Recall Kit contains:

2 ea. step tread screws with washers
2 ea. nylon caps
2 ea. clips, with 4 screws



Obtain Locally

1 tube Loctite Power Grab
6 ea. Pin Nails 1"



Warranty Labor Allowance:

Recall 221104REV Securing the Interior Step Tread

Use Flat Rate Codes:

6308 - 11	Inspected/Not Defective	0.4 hr.	Prior Authorization Required
6308 - 12	Inspected/Defective/Repaired	1.0 hr.	Prior Authorization Required

*If you have any questions concerning this bulletin, contact Dealer Technical Support:
Dealer Technical Support 1-800-816-9825*

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Bounder

REV Unit Identification #	Chassis VIN #
739FN4437218	1F66F5DN7M0
739CN4437220	1F66F5DN9M0
739CN4437223	1F66F5DN2M0
739FN4437227	1F66F5DN3M0
739CN4437229	1F66F5DN3M0
739KN4437231	1F66F5DN7M0
739KN4437232	1F66F5DN2M0
739KN4437233	1F66F5DN0M0
739KN4437235	1F66F5DN3M0
739CN4437236	1F66F5DN3M0
739KN4437237	1F66F5DN2M0
739KN4437238	1F66F5DN3M0
739KN4437247	1F66F5DN4M0
739KN4437250	1F66F5DN4M0
739KN4437253	1F66F5DN2M0
739KN4437256	1F66F5DN6M0
739KN4437259	1F66F5DN8M0
739FN4437262	1F66F5DN5M0
739CN4437265	1F66F5DN7M0
739CN4437268	1F66F5DN4M0
739CN4437271	1F66F5DN7M0
739CN4437274	1F66F5DN6M0
739CN4437377	1F66F5DN4M0
739CN4437382	1F66F5DN1M0
739FN4437385	1F66F5DN7M0
739CN4437387	1F66F5DN2M0
739CN4437390	1F66F5DN7M0
739KN4437393	1F66F5DN1M0
739FN4437396	1F66F5DN3M0
739KN4437398	1F66F5DN8M0
739KN4437401	1F66F5DN5M0
739KN4437427	1F66F5DN6M0
739CN4437430	1F66F5DN9M0
739CN4437434	1F66F5DN4M0
739CN4437436	1F66F5DN0M0

REV Unit Identification #	Chassis VIN #
739FN4437437	1F66F5DN5M0
739KN4437439	1F66F5DN4M0
739KN4437440	1F66F5DN2M0
739KN4437441	1F66F5DN4M0
739KN4437442	1F66F5DN6M0
739CN4437455	1F66F5DN6M0
739CN4437459	1F66F5DN8M0
739KN4437463	1F66F5DN8M0
739KN4437470	1F66F5DN4M0
739KN4437472	1F66F5DN7M0
739KN4437473	1F66F5DN2M0
739KN4437474	1F66F5DN8M0
739KN4437475	1F66F5DN5M0
739KN4437476	1F66F5DN2M0
739CN4437480	1F66F5DN9M0
739CN4437485	1F66F5DN3M0
739CN4437489	1F66F5DNXM0
739CN4437567	1F66F5DN6M0
739CN4437568	1F66F5DNXM0
739FN4437585	1F66F5DN4M0
739FN4437595	1F66F5DN1M0
739CN4437597	1F66F5DN8M0
739KN4437599	1F66F5DN1M0
739KN4437721	1F66F5DN2M0
739KN4437723	1F66F5DN3M0
739CN4437725	1F66F5DN2M0
739CN4437726	1F66F5DN9M0
739KN4437728	1F66F5DN4M0
739KN4437730	1F66F5DN6M0
739CN4437767	1F66F5DN7M0
739KN4437769	1F66F5DN9M0
739CN4437771	1F66F5DN3M0
739KN4437773	1F66F5DN1M0
739CN4437792	1F66F5DN9M0
739FN4437794	1F66F5DNXM0

771TG4420945 4UZFCGCY5GC [REDACTED]
 771AG442100 4UZACGCY6GC [REDACTED]
 (2022 Fleetwood Bounder serial numbers continued on next page)

771GG442100 3	4UZFCGCYXGC [REDACTED]
------------------	------------------------

771TG442100 5	4UZFCGCY1GC [REDACTED]
------------------	------------------------

771GG442104 8	4UZFCGCY7GC [REDACTED]
------------------	------------------------

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Bounder (continued)

REV Unit Identification #	Chassis VIN #	REV Unit Identification #	Chassis VIN #
739KN4437796	1F66F5DN2M0	739GN4438022	1F66F5DN1M0
739KN4437799	1F66F5DN1M0	739KN4438023	1F66F5DN5M0
739FN4437801	1F66F5DN6M0	739CN4438038	1F66F5DNXM0
739KN4437816	1F66F5DN8M0	739CN4438041	1F66F5DN6M0
739CN4437839	1F66F5DN0M0	739FN4438043	1F66F5DN3M0
739KN4437841	1F66F5DN1M0	739KN4438045	1F66F5DN9M0
739CN4437844	1F66F5DN6M0	739KN4438047	1F66F5DNXM0
739KN4437846	1F66F5DN4M0	739KN4438049	1F66F5DNXM0
739CN4437849	1F66F5DN1M0	739FN4438051	1F66F5DN2M0
739GN4437851	1F66F5DN8M0	739KN4438053	1F66F5DN6M0
739KN4437854	1F66F5DN8M0	739KN4438055	1F66F5DN9M0
739FN4437856	1F66F5DNXM0	739CN4438089	1F66F5DN8M0
739KN4437861	1F66F5DN5M0	739CN4438094	1F66F5DN3M0
739KN4437879	1F66F5DN7M0	739CN4438096	1F66F5DNXM0
739KN4437881	1F66F5DN3M0	739KN4438098	1F66F5DN2M0
739CN4437883	1F66F5DN1M0	739FN4438099	1F66F5DN4M0
739FN4437885	1F66F5DN4M0	739KN4438101	1F66F5DN4M0
739FN4437891	1F66F5DN6M0	739KN4438102	1F66F5DN6M0
739KN4437893	1F66F5DN9M0	739KN4438103	1F66F5DN7M0
739KN4437895	1F66F5DN7M0	739KN4438104	1F66F5DN9M0
739CN4437897	1F66F5DN8M0	739KN4438105	1F66F5DN4M0
739KN4437901	1F66F5DN2M0	739KN4438106	1F66F5DN6M0
739KN4437903	1F66F5DN3M0	739KN4438108	1F66F5DN8M0
739KN4437905	1F66F5DN4M0	739KN4438110	1F66F5DNXM0
739KN4437911	1F66F5DN5M0	739CN4438125	1F66F5DN5M0
739KN4437913	1F66F5DN2M0	739CN4438127	1F66F5DN7M0
739KN4437915	1F66F5DN4M0	739CN4438129	1F66F5DN1M0
739KN4437923	1F66F5DN0M0	739KN4438131	1F66F5DN0M0
739KN4437926	1F66F5DN0M0	739KN4438133	1F66F5DN5M0
739KN4437964	1F66F5DN2M0	739KN4438135	1F66F5DN1M0
739CN4438004	1F66F5DN6M0	739CN4438148	1F66F5DN5M0
739KN4438006	1F66F5DN9M0	739KN4438152	1F66F5DN8M0
739FN4438008	1F66F5DN3M0	739KN4438154	1F66F5DN1M0
739FN4438016	1F66F5DN5M0	739KN4438156	1F66F5DN3M0
739CN4438019	1F66F5DN8M0	739KN4438159	1F66F5DNXM0

(2022 Fleetwood Bounder serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Bouncer (continued)

REV Unit Identification #	Chassis VIN #
739KN4438161	1F66F5DN1M0
739CN4438186	1F66F5DN3M0
739CN4438189	1F66F5DN1M0
739KN4438191	1F66F5DN7M0
739FN4438194	1F66F5DN7M0
739KN4438196	1F66F5DN3M0
739KN4438198	1F66F5DN7M0
739KN4438202	1F66F5DN9M0
739KN4438207	1F66F5DN7M0
739CN4438229	1F66F5DN3M0
739FN4438231	1F66F5DN0M0
739CN4438233	1F66F5DN6M0
739KN4438235	1F66F5DN1M0
739KN4438239	1F66F5DN4M0
739KN4438241	1F66F5DN1M0
739KN4438274	1F66F5DN8M0
739KN4438275	1F66F5DN9M0
739FN4438276	1F66F5DN4M0
739CN4438300	1F66F5DN6M0
739KN4438302	1F66F5DN8M0
739KN4438308	1F66F5DN6M0
739CN4438331	1F66F5DN1M0
739KN4438333	1F66F5DN3M0
739KN4438335	1F66F5DN7M0
739KN4438338	1F66F5DN6M0
739KN4438340	1F66F5DNXM0
739KN4438342	1F66F5DN0M0
739CN4438356	1F66F5DN8M0
739CN4438360	1F66F5DN4M0
739KN4438362	1F66F5DN2M0
739KN4438363	1F66F5DN4M0
739KN4438364	1F66F5DN7M0
739KN4438365	1F66F5DN0M0
739KN4438366	1F66F5DN2M0
739KN4438386	1F66F5DN1M0

REV Unit Identification #	Chassis VIN #
739KN4438387	1F66F5DN9M0
739KN4438389	1F66F5DN0M0
739FN4438391	1F66F5DN5M0
739KN4438393	1F66F5DN2M0
739KN4438395	1F66F5DN3M0
739CN4438402	1F66F5DN4M0
739CN4438403	1F66F5DN2M0
739CN4438404	1F66F5DN5M0
739KN4438424	1F66F5DN6M0
739KN4438427	1F66F5DN4M0
739GN4438429	1F66F5DNXM0
739CN4438432	1F66F5DN8M0
739CN4438434	1F66F5DNXM0
739CN4438437	1F66F5DN7M0
739KN4438440	1F66F5DN6M0
739KN4438443	1F66F5DN2M0
739KN4438448	1F66F5DN3M0
739FN4438455	1F66F5DN8M0
739KN4438493	1F66F5DN1M0
739KN4438494	1F66F5DN1M0
739KN4438496	1F66F5DN4M0
739KN4438497	1F66F5DN8M0
739KN4438499	1F66F5DNXM0
739FN4438501	1F66F5DN4M0
739CN4438529	1F66F5DN6N0
739KN4438532	1F66F5DN2M0
739KN4438538	1F66F5DN8M0
739GN4438540	1F66F5DN6M0
739KN4438541	1F66F5DN6M0
739KN4438543	1F66F5DN8M0
739FN4438567	1F66F5DN8M0
739FN4438570	1F66F5DN1M0
739GN4438575	1F66F5DN8N0
739KN4438604	1F66F5DN1M0
739KN4438608	1F66F5DN4M0
739FN4438613	1F66F5DNXN0
739CN4438622	1F66F5DN5M0
739KN4438646	1F66F5DN9N0
739KN4438649	1F66F5DN1N0
739FN4438652	1F66F5DNXN0
739GN4438660	1F66F5DN1N0
739CN4438681	1F66F5DN3N0
739KN4438684	1F66F5DN3N0
739KN4438686	1F66F5DN3N0

(2022 Fleetwood Bouncer serial numbers)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Bounder (continued)

REV Unit Identification #	Chassis VIN #	REV Unit Identification #	Chassis VIN #
739FN4438613	1F66F5DNXN0	739CN4438763	1F66F5DN1N0
739CN4438622	1F66F5DN5N0	739KN4438765	1F66F5DNXN0
739KN4438646	1F66F5DN9N0	739GN4438767	1F66F5DN8N0
739KN4438649	1F66F5DN1N0	739KN4438769	1F66F5DN7N0
739FN4438652	1F66F5DNXN0	739KN4438771	1F66F5DN2N0
739GN4438660	1F66F5DN1N0	739GN4438775	1F66F5DN6N0
739CN4438681	1F66F5DN3N0	739FN4438778	1F66F5DN9N0
739KN4438684	1F66F5DN3N0	739CN4438804	1F66F5DN0N0
739KN4438686	1F66F5DN3N0	739CN4438806	1F66F5DN2N0
739KN4438688	1F66F5DN5N0	739KN4438809	1F66F5DN8N0
739KN4438690	1F66F5DN0N0	739KN4438811	1F66F5DN0N0
739KN4438720	1F66F5DN4N0	739KN4438814	1F66F5DN0N0
739KN4438723	1F66F5DN5N0	739CN4438817	1F66F5DN6N0
739GN4438726	1F66F5DN4N0	739CN4438819	1F66F5DN8N0
739KN4438729	1F66F5DN2N0	739CN4438821	1F66F5DN4N0
739KN4438731	1F66F5DN4N0	739KN4438833	1F66F5DN5N0
739GN4438735	1F66F5DN1N0	739KN4438835	1F66F5DNXN0
739CN4438737	1F66F5DN0N0	739KN4438837	1F66F5DN0N0
739GN4438761	1F66F5DN6N0	739KN4438839	1F66F5DN0N0

Model Year 2023 Fleetwood Bounder

REV Unit Identification #	Chassis VIN #	REV Unit Identification #	Chassis VIN #
739KP4438869	1F66F5DN0N0	739GP4438916	1F66F5DN3N0
739KP4438872	1F66F5DN2N0	739KP4438943	1F66F5DN1N0
739KP4438875	1F66F5DN6N0	739KP4438945	1F66F5DN2N0
739KP4438876	1F66F5DN1N0	739KP4438947	1F66F5DN4N0
739GP4438882	1F66F5DN1N0	739CP4438949	1F66F5DNXN0
739KP4438904	1F66F5DN6N0	739CP4438950	1F66F5DN1N0
739GP4438906	1F66F5DNXN0	739CP4438952	1F66F5DN7N0
739KP4438908	1F66F5DN2N0	739CP4438953	1F66F5DN5N0
739KP4438911	1F66F5DN9N0	739GP4438954	1F66F5DN5N0
739KP4438914	1F66F5DN5N0	739CP4438975	1F66F5DN8N0

(2023 Fleetwood Bounder serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2023 Fleetwood Bounder (continued)

REV Unit Identification #	Chassis VIN #
739KP4438978	1F66F5DN7N0
739KP4438982	1F66F5DN8N0
739CP4439003	1F66F5DN2N0
739KP4439005	1F66F5DN9N0
739CP4439007	1F66F5DN4N0
739KP4439017	1F66F5DN5N0
739KP4439018	1F66F5DN0M0
739KP4439019	1F66F5DNXN0
739KP4439025	1F66F5DN1N0
739KP4439027	1F66F5DN7N0
739KP4439029	1F66F5DN1N0
739KP4439031	1F66F5DN5N0
739CP4439034	1F66F5DN1N0
739KP4439065	1F66F5DNXN0
739KP4439067	1F66F5DN8N0
739KP4439069	1F66F5DN3N0
739CP4439088	1F66F5DN4N0
739CP4439090	1F66F5DN8N0

REV Unit Identification #	Chassis VIN #
739KP4439092	1F66F5DN5N0
739KP4439094	1F66F5DN9N0
739KP4439096	1F66F5DN0N0
739KP4439098	1F66F5DN2N0
739CP4439136	1F66F5DN1N0
739KP4439151	1F66F5DN7N0
739KP4439153	1F66F5DN6N0
739CP4439155	1F66F5DNXN0
739KP4439157	1F66F5DN8N0
739CP4439184	1F66F5DN9N0
739KP4439186	1F66F5DN2N0
739CP4439188	1F66F5DN5N0
739CP4439200	1F66F5DN7N0
739KP4439202	1F66F5DN3N0
739KP4439203	1F66F5DN0N0
739KP4439204	1F66F5DN5N0
739KP4439210	1F66F5DN0N0

Model Year 2022 Fleetwood Fortis

REV Unit Identification #	Chassis VIN #
764HN4437216	1F66F5DN4M0
764RN4437221	1F66F5DNXM0
764MN4437222	1F66F5DNXM0
764RN4437234	1F66F5DN1M0
764HN4437240	1F66F5DN8M0
764HN4437243	1F66F5DN5M0
764RN4437255	1F66F5DN5M0
764HN4437258	1F66F5DN7M0
764MN4437261	1F66F5DN7M0
764MN4437267	1F66F5DN2M0
764MN4437270	1F66F5DN4M0
764RN4437332	1F66F5DNXM0

REV Unit Identification #	Chassis VIN #
764HN4437333	1F66F5DN0M0
764HN4437335	1F66F5DN1M0
764DN4437337	1F66F5DN3M0
764HN4437338	1F66F5DN0M0
764HN4437339	1F66F5DN2M0
764DN4437341	1F66F5DN3M0
764RN4437350	1F66F5DNXM0
764MN4437352	1F66F5DN6M0
764MN4437354	1F66F5DN3M0
764MN4437356	1F66F5DN6M0
764RN4437358	1F66F5DN1M0
764HN4437359	1F66F5DN8M0

(2022 Fleetwood Fortis serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Fortis

REV Unit Identification #	Chassis VIN #
764HN4437361	1F66F5DN2M0
764HN4437362	1F66F5DN3M0
764RN4437378	1F66F5DN5M0
764DN4437383	1F66F5DN5M0
764MN4437386	1F66F5DN2M0
764RN4437389	1F66F5DN8M0
764RN4437392	1F66F5DNXM0
764RN4437394	1F66F5DN3M0
764RN4437397	1F66F5DN6M0
764RN4437400	1F66F5DN3M0
764DN4437429	1F66F5DN0M0
764RN4437433	1F66F5DN2M0
764MN4437481	1F66F5DN2M0
764MN4437497	1F66F5DNXM0
764MN4437518	1F66F5DN6M0
764MN4437521	1F66F5DN8M0
764MN4437523	1F66F5DNXM0
764MN4437572	1F66F5DN9L0
764RN4437645	1F66F5DN1M0
764DN4437646	1F66F5DN1M0
764RN4437694	1F66F5DN0M0
764MN4437695	1F66F5DN6M0
764RN4437698	1F66F5DNXM0
764RN4437700	1F66F5DNXM0
764DN4437701	1F66F5DN9M0
764MN4437727	1F66F5DNXM0
764MN4437765	1F66F5DN8M0
764RN4437775	1F66F5DN0M0
764DN4437793	1F66F5DN9M0
764DN4437798	1F66F5DN1M0
764MN4437802	1F66F5DN1M0
764DN4437808	1F66F5DN7M0
764DN4437837	1F66F5DN6M0
764RN4437840	1F66F5DN2M0
764DN4437842	1F66F5DN1M0

REV Unit Identification #	Chassis VIN #
764MN4437845	1F66F5DN1M0
764MN4437855	1F66F5DN9M0
764MN4437886	1F66F5DN3M0
764RN4437894	1F66F5DN0M0
764DN4437896	1F66F5DN0M0
764DN4437902	1F66F5DN1M0
764DN4437904	1F66F5DN7M0
764RN4437918	1F66F5DN7M0
764DN4437920	1F66F5DN9M0
764MN4437925	1F66F5DNXM0
764DN4437929	1F66F5DN5M0
764HN4437946	1F66F5DN4M0
764MN4437952	1F66F5DN4M0
764MN4437965	1F66F5DN8M0
764DN4437969	1F66F5DN4M0
764DN4438000	1F66F5DNXM0
764RN4438007	1F66F5DN7M0
764HN4438010	1F66F5DN9M0
764RN4438012	1F66F5DN6M0
764MN4438015	1F66F5DN1M0
764DN4438017	1F66F5DN0M0
764DN4438024	1F66F5DN0M0
764RN4438037	1F66F5DN8M0
764MN4438044	1F66F5DN0M0
764RN4438048	1F66F5DNXM0
764RN4438060	1F66F5DN7M0
764MN4438112	1F66F5DN5M0
764DN4438155	1F66F5DN9M0
764DN4438187	1F66F5DN4M0
764RN4438272	1F66F5DN6M0
764DN4438299	1F66F5DN6M0
764HN4438330	1F66F5DNXM0
764HN4438332	1F66F5DN3M0
764HN4438334	1F66F5DN5M0
764MN4438426	1F66F5DNXM0

(2022 Fleetwood Fortis serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Fortis (continued)

REV Unit Identification #	Chassis VIN #
764MN4438430	1F66F5DN4M0
764RN4438433	1F66F5DN4M0
764RN4438495	1F66F5DN3M0
764DN4438498	1F66F5DN1M0
764MN4438528	1F66F5DN0M0
764MN4438531	1F66F5DN0M0
764MN4438533	1F66F5DN4M0
764MN4438536	1F66F5DN9M0
764MN4438564	1F66F5DN9M0
764MN4438568	1F66F5DNXM0
764RN4438571	1F66F5DN8M0
764DN4438577	1F66F5DN3M0
764DN4438605	1F66F5DN1M0
764DN4438610	1F66F5DN1M0
764MN4438643	1F66F5DN2M0
764DN4438645	1F66F5DNXM0
764RN4438650	1F66F5DN7N0
764MN4438682	1F66F5DN5M0
764MN4438685	1F66F5DN5M0

REV Unit Identification #	Chassis VIN #
764DN4438695	1F66F5DN1M0
764MN4438721	1F66F5DN7M0
764MN4438724	1F66F5DN2M0
764MN4438727	1F66F5DN7M0
764DN4438730	1F66F5DNXM0
764MN4438764	1F66F5DN9M0
764MN4438766	1F66F5DN3M0
764RN4438772	1F66F5DN5N0
764DN4438774	1F66F5DN3M0
764DN4438776	1F66F5DN6M0
764RN4438805	1F66F5DN4N0
764MN4438812	1F66F5DN6M0
764MN4438815	1F66F5DN7M0
764RN4438818	1F66F5DN2N0
764MN4438822	1F66F5DN0M0
764MN4438826	1F66F5DN1M0
764MN4438832	1F66F5DN8M0
764MN4438836	1F66F5DNXM0

Model Year 2023 Fleetwood Fortis

REV Unit Identification #	Chassis VIN #
764MP4438868	1F66F5DN6N0
764MP4438874	1F66F5DN1N0
764MP4438905	1F66F5DN8N0
764MP4438907	1F66F5DNXN0
764DP4438910	1F66F5DN4N0
764MP4438912	1F66F5DN0N0
764RP4438935	1F66F5DN3N0
764RP4438944	1F66F5DN1N0
764MP4438987	1F66F5DNXN0

REV Unit Identification #	Chassis VIN #
764MP4439023	1F66F5DN1N0
764RP4439064	1F66F5DN7N0
764RP4439093	1F66F5DN5N0
764MP4439097	1F66F5DN2N0
764MP4439100	1F66F5DN9N0
764RP4439107	1F66F5DNXN0
764MP4439135	1F66F5DN3N0
764DP4439181	1F66F5DN4N0

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Fleetwood Southwind

REV Unit Identification #	Chassis VIN #
721KN4437215	1F66F5DN2M0
721KN4437217	1F66F5DN3M0
721CN4437380	1F66F5DN5M0
721CN4437457	1F66F5DN6M0
721KN4437465	1F66F5DN2M0
721KN4437468	1F66F5DNXM0
721CN4437569	1F66F5DN6M0
721CN4437570	1F66F5DN8M0
721CN4437571	1F66F5DN4M0
721CN4437734	1F66F5DN5M0
721KN4437739	1F66F5DN3M0
721CN4437776	1F66F5DN2M0
721KN4437777	1F66F5DN1M0
721KN4437780	1F66F5DN0M0
721CN4437804	1F66F5DN2M0
721KN4437807	1F66F5DN0M0
721KN4437811	1F66F5DN6M0
721KN4437888	1F66F5DN7M0
721CN4437906	1F66F5DNXM0

REV Unit Identification #	Chassis VIN #
721KN4437953	1F66F5DN8M
721FN4437970	1F66F5DNXM
721KN4438057	1F66F5DN3M
721FN4438092	1F66F5DN9M
721CN4438150	1F66F5DN5M
721CN4438204	1F66F5DN9M
721CN4438237	1F66F5DN3M
721KN4438277	1F66F5DN4M
721FN4438278	1F66F5DN2M
721CN4438328	1F66F5DN9M
721KN4438457	1F66F5DN1M
721FN4438508	1F66F5DNXM
721CN4438572	1F66F5DN8N0
721KN4438576	1F66F5DNXM
721KN4438606	1F66F5DN6M
721FN4438642	1F66F5DN8N0
721KN4438692	1F66F5DN2N0
721KN4438739	1F66F5DN7N0
721KN4438740	1F66F5DN9N0

Model Year 2023 Fleetwood Southwind

REV Unit Identification #	Chassis VIN #
721KP4438977	1F66F5DN7N0
721KP4439040	1F66F5DN3N0
721KP4439041	1F66F5DN5N0
721KP4439042	1F66F5DN3N0
721CP4439076	1F66F5DN2N0

REV Unit Identification #	Chassis VIN #
721KP4439102	1F66F5DN4N0
721KP4439104	1F66F5DN9N0
721KP4439127	1F66F5DN3N0
721FP4439132	1F66F5DN8N0
721KP4439178	1F66F5DN5N0

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Holiday Rambler Invicta

REV Unit Identification #	Chassis VIN #
664HN4437225	1F66F5DN6M0
664MN4437230	1F66F5DN1M0
664RN4437246	1F66F5DN6M0
664MN4437249	1F66F5DN5M0
664MN4437252	1F66F5DN3M0
664RN4437264	1F66F5DN6M0
664HN4437272	1F66F5DN9M0
664HN4437275	1F66F5DN7M0
664HN4437340	1F66F5DN9M0
664MN4437342	1F66F5DN1M0
664MN4437343	1F66F5DN4M0
664RN4437381	1F66F5DNXM0
664RN4437438	1F66F5DN4M0
664DN4437456	1F66F5DN7M0
664HN4437462	1F66F5DN0M0
664MN4437488	1F66F5DN3M0
664MN4437493	1F66F5DN7M0
664MN4437495	1F66F5DN5M0
664MN4437526	1F66F5DN1M0
664MN4437528	1F66F5DN9M0
664MN4437531	1F66F5DN0M0
664MN4437533	1F66F5DN4M0
664HN4437648	1F66F5DN3M0
664MN4437649	1F66F5DN4M0
664MN4437805	1F66F5DN6M0
664MN4437812	1F66F5DN2M0
664MN4437815	1F66F5DN4M0
664DN4437847	1F66F5DN3M0
664HN4437857	1F66F5DNXM0
664RN4437882	1F66F5DN5M0
664DN4437889	1F66F5DN2M0
664DN4437922	1F66F5DN7M0
664MN4437967	1F66F5DNXM0
664DN4437996	1F66F5DN8M0
664RN4438003	1F66F5DN8M0

REV Unit Identification #	Chassis VIN #
664MN4438020	1F66F5DN0M0
664HN4438040	1F66F5DN9M0
664DN4438052	1F66F5DN2M0
664DN4438064	1F66F5DN7M0
664RN4438088	1F66F5DN0M0
664MN4438091	1F66F5DN3M0
664HN4438132	1F66F5DN3M0
664HN4438192	1F66F5DN1M0
664DN4438234	1F66F5DN2M0
664MN4438240	1F66F5DN2M0
664MN4438273	1F66F5DNXM0
664RN4438285	1F66F5DN4M0
664MN4438304	1F66F5DN5M0
664RN4438307	1F66F5DN7M0
664HN4438337	1F66F5DNXM0
664HN4438339	1F66F5DNXM0
664DN4438341	1F66F5DN6M0
664HN4438390	1F66F5DN2M0
664MN4438394	1F66F5DN4M0
664DN4438436	1F66F5DN7M0
664MN4438439	1F66F5DN5M0
664DN4438441	1F66F5DN4M0
664RN4438445	1F66F5DN2M0
664DN4438446	1F66F5DN8M0
664RN4438449	1F66F5DN5M0
664MN4438500	1F66F5DN3M0
664DN4438506	1F66F5DN5M0
664RN4438539	1F66F5DNXM0
664MN4438542	1F66F5DN8M0
664RN4438544	1F66F5DN8M0
664DN4438573	1F66F5DN3M0
664HN4438579	1F66F5DN8M0
664DN4438581	1F66F5DN3M0
664MN4438583	1F66F5DN3M0
664DN4438584	1F66F5DN2M0

(2022 Holiday Rambler Invicta serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Holiday Rambler Invicta (continued)

REV Unit Identification #	Chassis VIN #
664MN4438614	1F66F5DN8M0
664RN4438619	1F66F5DN9M0
664DN4438621	1F66F5DNXM0
664MN4438648	1F66F5DN6M0
664MN4438653	1F66F5DN7M0
664MN4438657	1F66F5DN5M0
664DN4438659	1F66F5DN8M0
664MN4438687	1F66F5DN3M0
664MN4438689	1F66F5DN1M0
664MN4438691	1F66F5DN4M0
664MN4438693	1F66F5DN4M0
664DN4438697	1F66F5DN5M0

REV Unit Identification #	Chassis VIN #
664DN4438699	1F66F5DN9M0
664HN4438732	1F66F5DN1N0
664MN4438734	1F66F5DN9M0
664HN4438736	1F66F5DN9N0
664MN4438738	1F66F5DN5M0
664MN4438768	1F66F5DN1M0
664DN4438780	1F66F5DN4M0
664RN4438808	1F66F5DN8N0
664MN4438810	1F66F5DN6M0
664RN4438830	1F66F5DN3N0
664RN4438834	1F66F5DN7N0
664HN4438838	1F66F5DN6N0

Model Year 2023 Holiday Rambler Invicta

REV Unit Identification #	Chassis VIN #
664DP4438871	1F66F5DN4N0
664MP4438879	1F66F5DN2N0
664MP4438901	1F66F5DN8N0
664DP4438903	1F66F5DN0N0
664HP4438976	1F66F5DN5N0

REV Unit Identification #	Chassis VIN #
664MP4438985	1F66F5DN7M0
664DP4439006	1F66F5DN3M0
664DP4439177	1F66F5DN5N0
664DP4439214	1F66F5DN7N0

Model Year 2022 Holiday Rambler Vacationer

REV Unit Identification #	Chassis VIN #
623FN4437241	1F66F5DN5M0
623CN4437244	1F66F5DN2M0
623KN4437423	1F66F5DN0M0
623KN4437425	1F66F5DN2M0
623FN4437432	1F66F5DN1M0
623FN4437453	1F66F5DNXM0
623FN4437460	1F66F5DN3M0
623FN4437466	1F66F5DN3M0
623CN4437600	1F66F5DN0M0

REV Unit Identification #	Chassis VIN #
623FN4437647	1F66F5DN2M0
623KN4437732	1F66F5DN0M0
623CN4437736	1F66F5DN5M0
623KN4437737	1F66F5DN2M0
623KN4437738	1F66F5DN1M0
623FN4437774	1F66F5DNXM0
623FN4437779	1F66F5DN6M0
623FN4437809	1F66F5DN8M0
623FN4437813	1F66F5DN8M0

(2022 Holiday Rambler Vacationer serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Holiday Rambler Vacationer (continued)

REV Unit Identification #	Chassis VIN #
623FN4437647	1F66F5DN2M0
623KN4437732	1F66F5DN0M0
623CN4437736	1F66F5DN5M0
623KN4437737	1F66F5DN2M0
623KN4437738	1F66F5DN1M0
623FN4437774	1F66F5DNXM0
623FN4437779	1F66F5DN6M0
623FN4437809	1F66F5DN8M0
623FN4437813	1F66F5DN8M0
623CN4437814	1F66F5DN4M0
623KN4437852	1F66F5DN6M0
623CN4437858	1F66F5DN4M0
623KN4437859	1F66F5DN3M0
623KN4437917	1F66F5DN3M0
623KN4437928	1F66F5DN4M0
623FN4437998	1F66F5DN1M0
623KN4438002	1F66F5DN6M0
623CN4438011	1F66F5DN8M0
623CN4438013	1F66F5DN6M0
623KN4438059	1F66F5DN5M0
623KN4438061	1F66F5DN9M0
623CN4438063	1F66F5DN8M0
623CN4438065	1F66F5DNXM0
623FN4438158	1F66F5DN0M0
623KN4438163	1F66F5DN3M0
623KN4438164	1F66F5DN5M0
623CN4438166	1F66F5DN7M0
623FN4438200	1F66F5DN9M0
623KN4438205	1F66F5DN5M0
623KN4438243	1F66F5DN5M0
623FN4438305	1F66F5DN3M0
623CN4438310	1F66F5DN0M0
623KN4438312	1F66F5DN6M0
623FN4438358	1F66F5DN2M0
623KN4438367	1F66F5DN4M0

REV Unit Identification #	Chassis VIN #
623KN4438368	1F66F5DN8M0
623KN4438397	1F66F5DN5M0
623KN4438398	1F66F5DN1M0
623KN4438399	1F66F5DN0M0
623CN4438401	1F66F5DN9M0
623GN4438442	1F66F5DN1M0
623GN4438447	1F66F5DN6M0
623KN4438450	1F66F5DN0M0
623KN4438451	1F66F5DN0M0
623CN4438453	1F66F5DN2M0
623CN4438454	1F66F5DN6M0
623KN4438456	1F66F5DN2M0
623KN4438502	1F66F5DN6M0
623KN4438503	1F66F5DN7M0
623KN4438504	1F66F5DN9M0
623KN4438505	1F66F5DNXM0
623CN4438507	1F66F5DNXM0
623CN4438509	1F66F5DN1M0
623FN4438535	1F66F5DN3M0
623KN4438545	1F66F5DN9M0
623KN4438546	1F66F5DN8M0
623CN4438578	1F66F5DN4N0
623FN4438580	1F66F5DN8N0
623KN4438582	1F66F5DN4M0
623KN4438611	1F66F5DN4M0
623KN4438615	1F66F5DNXM0
623KN4438618	1F66F5DN2M0
623KN4438620	1F66F5DN7N0
623KN4438655	1F66F5DN5N0
623FN4438658	1F66F5DNXN0
623KN4438694	1F66F5DN3N0
623KN4438733	1F66F5DN6N0
623KN4438773	1F66F5DN7N0
623CN4438777	1F66F5DNXN0
623CN4438779	1F66F5DN9N0

(2022 Holiday Rambler Vacationer serial numbers continued on next page)

Recall 221104REV Affected Unit Serial Numbers

Model Year 2022 Holiday Rambler Vacationer (continued)

REV Unit Identification #	Chassis VIN #
623GN4438781	1F66F5DN0N0 [REDACTED]
623KN4438813	1F66F5DN9N0 [REDACTED]
623CN4438823	1F66F5DN8N0 [REDACTED]
623KN4438825	1F66F5DN3N0 [REDACTED]

REV Unit Identification #	Chassis VIN #
623KN4438827	1F66F5DN4N0 [REDACTED]
623KN4438829	1F66F5DNXN0 [REDACTED]
623KN4438831	1F66F5DN8N0 [REDACTED]

Model Year 2023 Holiday Rambler Vacationer

REV Unit Identification #	Chassis VIN #
623KP4438878	1F66F5DN6N0 [REDACTED]
623CP4438881	1F66F5DN6N0 [REDACTED]
623KP4438902	1F66F5DN3N0 [REDACTED]
623KP4438918	1F66F5DN0N0 [REDACTED]
623KP4438937	1F66F5DN1N0 [REDACTED]
623KP4438939	1F66F5DN1N0 [REDACTED]
623KP4438980	1F66F5DN7N0 [REDACTED]
623KP4438989	1F66F5DN9N0 [REDACTED]
623CP4439009	1F66F5DN9N0 [REDACTED]
623KP4439011	1F66F5DNXM0 [REDACTED]
623KP4439013	1F66F5DNXN0 [REDACTED]
623KP4439015	1F66F5DN5M0 [REDACTED]
623KP4439033	1F66F5DN3N0 [REDACTED]
623CP4439036	1F66F5DN6N0 [REDACTED]

REV Unit Identification #	Chassis VIN #
623CP4439038	1F66F5DN1N0 [REDACTED]
623KP4439071	1F66F5DN7N0 [REDACTED]
623KP4439073	1F66F5DN3N0 [REDACTED]
623CP4439074	1F66F5DNXN0 [REDACTED]
623CP4439106	1F66F5DNXN0 [REDACTED]
623CP4439108	1F66F5DN1N0 [REDACTED]
623KP4439109	1F66F5DNXN0 [REDACTED]
623CP4439128	1F66F5DN8N0 [REDACTED]
623KP4439130	1F66F5DN5N0 [REDACTED]
623CP4439133	1F66F5DN7N0 [REDACTED]
623CP4439137	1F66F5DN3N0 [REDACTED]
623CP4439150	1F66F5DN8N0 [REDACTED]
623KP4439180	1F66F5DN4N0 [REDACTED]
623KP4439182	1F66F5DN1N0 [REDACTED]