



November, 2022

\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \*

According to our records, your 2014 MKZ has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number 22S02 - Brake Stop Lamps Stay On**  
and Description:

**What is the issue?** The brake pedal stop bumper on your vehicle may disintegrate and fall off in certain high temperature, high humidity, and high salinity environments.

A missing brake pedal stop bumper will result in the brake stop lamps remaining on continuously, even when the brake pedal is not applied, which may confuse other drivers and increase the risk of a crash. On automatic transmission vehicles, a missing brake pedal bumper could allow the transmission to be shifted out of the "PARK" position without depressing the brake, which may result in a vehicle rollaway, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [lincoln.com/support](http://lincoln.com/support).

Thank you for your attention to this very important matter.

Noviembre de, 2022

\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \*

SegUR nuestros registros, no se realizaron en sur 2014 MKZ las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 22S02 - Las luces de freno permanecen encendidas

**¿Cuál es el problema?** La defensa del tope del pedal del freno de su vehículo podría desintegrarse y desprenderse cuando la temperatura es alta, cuando hay mucha humedad y en entornos de gran salinidad.

Al no encontrarse presente la defensa del tope del pedal del freno se podría producir el encendido permanente de las luces de freno, incluso cuando el pedal del freno no está aplicado, lo cual puede confundir a otros conductores y aumentar el riesgo de choque. Al no estar presente la defensa del pedal del freno en vehículos con transmisión automática, la transmisión podría salir de la posición de "ESTACIONAMIENTO" sin presionar el pedal del freno, lo cual hace posible el desplazamiento del vehículo, lo que aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](http://lincoln.com/support).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**

R K C


0017227 A / 000000000000175 / 175



[REDACTED]  
[REDACTED]  
[REDACTED]

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▼ THEN FOLD, REMOVE THESE SIDE EDGES FIRST  
CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▼ THEN FOLD, REMOVE THESE SIDE EDGES FIRST  
CREASE AND TEAR THIS STUB ALONG PERFORATION ▼