



March, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2014 MKZ has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **22S02 - Brake Stop Lamps Stay on - AND REGIONAL 22R01**

What is the issue? The brake pedal stop bumper on your vehicle may disintegrate and fall off in certain high temperature, high humidity, and high salinity environments.

A missing brake pedal stop bumper will result in the brake stop lamps remaining on continuously, even when the brake pedal is not applied, which may confuse other drivers and increase the risk of a crash. On automatic transmission vehicles, a missing brake pedal bumper could allow the transmission to be shifted out of the "PARK" position without depressing the brake, which may result in a vehicle rollaway, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Marzo de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2014 MKZ las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S02 - Las luces de freno permanecen encendidas - Y REGIONAL 22R01**

¿Cuál es el problema? La defensa del tope del pedal del freno de su vehículo podría desintegrarse y desprenderse cuando la temperatura es alta, cuando hay mucha humedad y en entornos de gran salinidad.

Al no encontrarse presente la defensa del tope del pedal del freno se podría producir el encendido permanente de las luces de freno, incluso cuando el pedal del freno no está aplicado, lo cual puede confundir a otros conductores y aumentar el riesgo de choque. Al no estar presente la defensa del pedal del freno en vehículos con transmisión automática, la transmisión podría salir de la posición de "ESTACIONAMIENTO" sin presionar el pedal del freno, lo cual hace posible el desplazamiento del vehículo, lo que aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atenció en este asunto sumamente importante.

1 of 2

00000000000207 / 413 / 207




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0657089 A / 000000000000207 / 207



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

