



December, 2024

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2022 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **22S23 - Power Head Restraint Bun Suspect Engagement to Mechanism**

**What is the issue?** On your vehicle, it may be possible for the front row driver and passenger seat head restraint cushion to detach from the head restraint when adjusted to the full forward position.

If your head restraint cushion detaches, the vehicle occupant will experience a loose head restraint cushion, and the cushion may fully detach, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [lincoln.com/support](https://lincoln.com/support).

Thank you for your attention to this very important matter.

December, 2024

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en su 2022 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **22S23 - Acoplamiento sospechoso del rodete de la cabecera eléctrica al mecanismo**

**¿Cuál es el problema?** Es posible que el cojín de la cabecera del asiento del conductor y del pasajero de la fila delantera de su vehículo se desprenda de la cabecera cuando se ajusta en la posición totalmente hacia adelante.

Si se desprende el cojín de la cabecera, el ocupante del vehículo sentirá que el cojín está flojo y este podría desprenderse por completo, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](https://lincoln.com/support).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0204924 A / 000000000000646 / 646



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

