



December, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **22S24 - Power Steering Column Squib Connector/Wiring**

What is the issue?

On your vehicle, it may be possible that the wiring harness for the collapsible steering column feature may be an incorrect length.



Airbag Warning Indicator

This may result in the wiring becoming damaged or disconnected if the power adjustable steering column is extended (adjusted outward). Damaged or disconnected wiring will illuminate the airbag warning indicator (shown on the left) and prevent the collapsible steering column feature from operating properly during certain crash conditions, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Diciembre de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S24 - Conector/cableado del detonador de la columna de la dirección eléctrica**

¿Cuál es el problema?

Es posible que el arnés para la función de la columna de la dirección plegable de su vehículo tenga una longitud incorrecta.



Indicador de alerta de bolsa de aire

Esto podría generar daño o la desconexión del cableado, si la columna de la dirección ajustable eléctrica se extiende (se ajusta hacia afuera). Un cableado dañado o desconectado encenderá el indicador de alerta de bolsa de aire (que aparece a la izquierda) e impedirá que la función de la columna de la dirección plegable funcione correctamente durante determinadas condiciones de choque, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0294781 A / 000000000000651 / 651



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

