



November, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2016 F-250 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **22S35 - Manufacturing Clockspring Contamination**
and Description:

What is the issue?



Airbag Warning Indicator

On your vehicle, dust contamination may lead to a loss of electrical circuit connection with your steering wheel and airbag and will illuminate your airbag warning light in your vehicle's instrument cluster (shown on the left).

If the airbag circuit disconnects, and a crash event of sufficient severity warrants a driver front airbag deployment, the airbag will not deploy. Failure of the driver airbag to deploy increases the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Noviembre de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2016 F-250 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S35 - Contaminación del resorte de reloj de fábrica**

¿Cuál es el problema?



Indicador de alerta de bolsa de aire

La contaminación de polvo de su vehículo podría ocasionar una pérdida de conexión del circuito eléctrico con el volante de dirección y la bolsa de aire, y encenderá la luz de alerta de la bolsa de aire en el tablero de instrumentos (aparece a la izquierda).

Si se desconecta el circuito de la bolsa de aire, en caso de ocurrir un choque de suficiente intensidad donde el despliegue de la bolsa de aire delantera del conductor debiese producirse, la bolsa de aire no se desplegará. Si no se despliega la bolsa de aire del conductor, el riesgo de sufrir lesiones en caso de choque aumenta.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0094982 A / 0000000000000001 / 1



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼