

**Daimler Truck North America LLC (DTNA)** on behalf of its Freightliner Truck Division, is reminding you that a defect which relates to motor vehicle safety exists on the vehicles mentioned in this notification.

DAIMLER TRUCK  
North America  
PO Box 5637  
Portland, OR 97228-9808

*USA Proof - 65 or Less*

***Please take this opportunity to contact an authorized DAIMLER TRUCK North America dealer to arrange to have recalls performed free of charge.***

FL937 EB3410-1

To locate an authorized dealer, search online at <https://northamerica.daimlertruck.com/contact-us/>

If you have questions regarding this recall, contact **DTNA Warranty Campaigns Department** at (800)547-0712, 7:00 am to 4:00 pm Pacific Time, Monday through Friday, email address: [DTNA.Warranty.Campaigns@DaimlerTruck.com](mailto:DTNA.Warranty.Campaigns@DaimlerTruck.com)

## ***Our Records Show Your Vehicle Has Not Been Repaired Nuestros Registros Muestran Que No Ha Reparado Su Vehículo***

**Campaign FL937 STEERING ASSEMBLY U-JOINT PINCH BOLTS**



# **Safety Recall Notice**

# **Aviso De Retirada De Seguridad**

**THIS IS AN IMPORTANT REMINDER NOTICE**

**ESTO ES UN AVISO RECORDATORIO IMPORTANTE**

***Please verify ownership and Vehicle Identification Number (VIN)***

***Verifique la propiedad y el Numero de Identificación Vehicular (NIV)***

**DAIMLER TRUCK North America LLC (DTNA)** en nombre de su división de camiones Freightliner, le recuerda que existe un defecto relacionado con la seguridad de los vehículos de motor en los vehículos mencionados en esta notificación.

***Aproveche esta oportunidad para comunicarse con un distribuidor autorizado de DAIMLER TRUCK North America para coordinar la realización de retiros del mercado sin cargo***

Para localizar un distribuidor autorizado, busque en línea en <https://northamerica.daimlertruck.com/contact-us/>

Si tiene alguna pregunta sobre este retiro del mercado, comuníquese con el Departamento de campañas de garantía al (800) 547-0712, de 7:00 a.m. a 4:00 p.m., hora de Pacífico. Hora, de lunes a viernes, dirección de correo electrónico: [DTNA.Warranty.Campaigns@DaimlerTruck.com](mailto:DTNA.Warranty.Campaigns@DaimlerTruck.com)

**DAIMLER TRUCK**

North America

PO Box 5637  
Portland, OR 97228-9808

**List of your vehicle(s) identification number (VIN) included in  
Lista del Numero de Identificación Vehicular (NIV) de su(s) vehículo(s) incluido en  
Campaign FL937 STEERING ASSEMBLY U-JOINT PINCH BOLTS**

*To Read the Owner's Letter, scan the DTNA QR code or visit  
Para leer la carta del propietario, escanee el código QR de DTNA o visite*

[www.DTNARecalls.com/FL937](http://www.DTNARecalls.com/FL937)



DTNA

*To check for additional recalls, scan the NHTSA QR code or visit  
Para verificar retiros adicionales, escanee el código QR de la NHTSA o visite*

[www.NHTSA.gov/recalls](http://www.NHTSA.gov/recalls)



NHTSA

**Daimler Truck North America LLC (DTNA)** on behalf of its Freightliner Truck Division, is reminding you that a defect which relates to motor vehicle safety exists on the vehicles mentioned in this notification.

DAIMLER TRUCK  
North America  
PO Box 5637  
Portland, OR 97228-9808

*USA Proof - 65 or More*

***Please take this opportunity to contact an authorized DAIMLER TRUCK North America dealer to arrange to have recalls performed free of charge.***

FL937 X09190-68

To locate an authorized dealer, search online at <https://northamerica.daimlertruck.com/contact-us/>

If you have questions regarding this recall, contact **DTNA Warranty Campaigns Department** at (800)547-0712, 7:00 am to 4:00 pm Pacific Time, Monday through Friday, email address: [DTNA.Warranty.Campaigns@DaimlerTruck.com](mailto:DTNA.Warranty.Campaigns@DaimlerTruck.com)

## ***Our Records Show Your Vehicle Has Not Been Repaired Nuestros Registros Muestran Que No Ha Reparado Su Vehículo***

**Campaign FL937 STEERING ASSEMBLY U-JOINT PINCH BOLTS**



# **Safety Recall Notice Aviso De Retirada De Seguridad**

**THIS IS AN IMPORTANT REMINDER NOTICE  
ESTO ES UN AVISO RECORDATORIO IMPORTANTE**

***Please verify ownership and Vehicle Identification Number (VIN)***

**Verifique la propiedad y el Numero de Identificación Vehicular (NIV)**

**DAIMLER TRUCK North America LLC (DTNA)** en nombre de su división de camiones Freightliner, le recuerda que existe un defecto relacionado con la seguridad de los vehículos de motor en los vehículos mencionados en esta notificación.

***Aproveche esta oportunidad para comunicarse con un distribuidor autorizado de DAIMLER TRUCK North America para coordinar la realización de retiros del mercado sin cargo***

Para localizar un distribuidor autorizado, busque en línea en <https://northamerica.daimlertruck.com/contact-us/>

Si tiene alguna pregunta sobre este retiro del mercado, comuníquese con el Departamento de campañas de garantía al (800) 547-0712, de 7:00 a.m. a 4:00 p.m., hora de Pacifico. Hora, de lunes a viernes, dirección de correo electrónico: [DTNA.Warranty.Campaigns@DaimlerTruck.com](mailto:DTNA.Warranty.Campaigns@DaimlerTruck.com)

**DAIMLER TRUCK**

North America

PO Box 5637  
Portland, OR 97228-9808

**List of your vehicle(s) identification number (VIN) included in  
Lista del Numero de Identificación Vehicular (NIV) de su(s) vehículo(s) incluido en  
Campaign FL937 STEERING ASSEMBLY U-JOINT PINCH BOLTS**

*To Read the Owner's Letter, scan the DTNA QR code or visit [www.DTNARecalls.com/FL937](http://www.DTNARecalls.com/FL937)*  
*Para leer la carta del propietario, escanee el código QR de DTNA o visite*



DTNA

**Our Records indicate you have more vehicles than listed above.**  
**Please contact DTNA Warranty Campaigns for a complete list of VINs**  
**Nuestros registros indican que tiene más vehículos que los enumerados anteriormente.**  
Comuníquese con Campañas de Garantía de DTNA para obtener una lista completa de NIVs.  
Email: [DTNA.Warranty.Campaigns@DaimlerTruck.com](mailto:DTNA.Warranty.Campaigns@DaimlerTruck.com) Call: (800)547-0712



NHSTA

*To check for additional recalls, scan the NHTSA QR code or visit [www.NHTSA.gov/recalls](http://www.NHTSA.gov/recalls)*  
*Para verificar retiros adicionales, escanee el código QR de la NHTSA o visite*