



February, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **22C13 - Front Apron Assembly**

What is the issue? Your vehicle may have been built with an engine frame rail that does not maintain its integrity in a crash and as a result does not meet the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 208 Occupant Crash Protection and FMVSS No. 301 Fuel System Integrity.

An engine frame rail that does not maintain its integrity in a crash increases the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22C13 - Ensamble del faldón delantero**

¿Cuál es el problema? Su vehículo pudo haber sido fabricado con un riel del bastidor del motor que no mantiene su integridad en caso de choque y, como resultado de esto, no cumple con los requisitos especificados en la norma federal de seguridad para vehículos de motor (FMVSS) n.º 208 Protección del ocupante en caso de impacto y FMVSS n.º 301 Integridad del sistema de combustible.

Un riel del bastidor del motor que no mantiene su integridad en una colisión aumenta el riesgo de sufrir lesiones en caso de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0447314 A / 000000000000146 / 146



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

