



November, 2022

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2022 Navigator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **22C14 - Headlamp Control Module Inop**

**What is the issue?** It may be possible for your vehicle to experience a loss of side marker lamps, daytime running lamps (if equipped), and/or other lighting features, due to a software error in the headlamp control module (HCM). If your vehicle experiences this concern, there will be a pop-up message in the cluster stating, "Advanced front lighting features temporarily unavailable".

This may result in a loss of function to side marker lamps and, daytime running lamps (if equipped), increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: [lincoln.com/support](http://lincoln.com/support).

Thank you for your attention to this very important matter.

Noviembre de, 2022

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2022 Navigator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **22C14 - Módulo de control de los faros no funciona**

**¿Cuál es el problema?** Es posible que su vehículo experimente una pérdida de las luces de posición laterales, luces de circulación diurna (si están equipadas) u otras funciones de las luces, debido a un error de software en el módulo de control de los faros (HCM). Si su vehículo experimenta este problema, en el tablero aparecerá un mensaje que señala "Función de luces delanteras avanzadas temporalmente no disponible".

Esto podría generar una pérdida de la función de las luces de posición laterales y de las luces de circulación diurna (si están equipadas), lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [lincoln.com/support](http://lincoln.com/support).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0150831 A / 000000000000164 / 164



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

