



IMPORTANT SAFETY RECALL NOTICE

SECOND NOTICE - ACTION REQUIRED

September 25, 2024

Lawrence,

Our records currently indicate you have not had this recall completed on your affected vehicle:

I-19-02

Indian Motorcycle has determined that all model year 2014-2020 (111 c.i.) motorcycles may experience loss of forward lighting. If this event does occur, the High Beam indicator will flash on the gauge cluster. If the motorcycle lighting malfunctions while in operation, it may reduce visibility and increase the risk of a crash.

To address this concern, Indian Motorcycle has authorized your dealer to inspect the VCM connector and update the VCM software. If the VCM connector is damaged, a new connector and VCM will be installed.

Contact your authorized Indian Motorcycle dealer to schedule an appointment to have the repairs performed. If you need assistance contacting or locating an Indian Motorcycle dealer, visit our [Dealer Locator](#) web page.

This work will be performed by your dealer at no cost to you.

For the latest update on this safety recall, visit our [Product Safety Recall](#) web page.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction for riders to enjoy.

-Indian Motorcycle

Received This Notice In Error?

This notice was sent according to our most current registration information. If you no longer own this vehicle, contact your dealer to complete a transfer of ownership. Federal law requires that

any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 working days after the day on which the notice is received.

You've received this email from Indian Motorcycle because you are a registered owner of a motorcycle affected by a recent safety recall notice.

Please do not reply to this email. To contact us, please call us at **1-800-POLARIS** or visit our [help page](#).

© 2024 Polaris Industries Inc. | 2100 Highway 55, Medina, MN 55340