



February, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Explorer has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number **22S60 - 2.3L High Pressure Fuel Line Suspect Torque**
and Description:

What is the issue?

On your vehicle, the high-pressure fuel tube connection to the high-pressure fuel pump and fuel rail may not be tightened to specification.



Service Engine Soon

If the connections are not tightened to specification, it may result in a fuel leak, fuel odor, or the vehicle may not start. Additionally, a fuel leak caused by low torque on the high-pressure fuel tube connections may illuminate the Service Engine Soon warning indicator (shown on the left) in the instrument cluster. A fuel leak in the presence of an ignition source increases the risk of fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 Explorer las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22S60 - Par de apriete sospechoso de la tubería de combustible de alta presión de 2.3L**

¿Cuál es el problema?

La conexión del tubo de combustible de alta presión a la bomba de combustible de alta presión y el riel de combustible de su vehículo podría no estar apretado según la especificación.



Servicio al motor a la brevedad

Si las conexiones no están apretadas según la especificación, se podría generar una fuga de combustible, olor a combustible o el vehículo podría no arrancar. Adicionalmente, una fuga de combustible ocasionada por un par de torsión bajo en las conexiones del tubo de combustible de alta presión podría encender el indicador de alerta de servicio al motor a la brevedad (mostrado a la izquierda) en el tablero de instrumentos. Una fuga de combustible en presencia de una fuente de encendido aumenta el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0958854 A / 000000000000475 / 475



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼



▼ REMOVE THESE SIDE EDGES FIRST
▼ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼