



Ford Motor Company  
Ford Customer Service Division  
P. O. Box 1904  
Dearborn, Michigan 48121 1904



771688040126

A/1/000001/1

October 2022



JOHN A. SAMPLE  
123 SAMPLE ST  
SAMPLE CITY, MI 12345-6789

**\*\*\* IMPORTANT SAFETY RECALL \*\*\***

**Safety Recall Notice 22S62 / NHTSA Recall 22V-731**

2021 Motorhome Chassis

Your Vehicle Identification Number (VIN): XXXXXXXXXX

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

**What is the issue?** On your vehicle, the rear stabilizer bar attachment bracket(s) may break and separate from the vehicle during usage.

**What is the risk?** If the rear stabilizer bar attachment bracket(s) break or separate from the vehicle, the driver will not experience a sudden change in vehicle dynamics and the vehicle will remain stable. However, a separation of the attachment bracket while driving can create a potential road hazard for other road users, increasing the risk of a crash.

**What will Ford and your dealer do?** Ford Motor Company is working closely with its suppliers to produce parts for this repair. When parts become available, Ford Motor Company will notify you via mail to schedule a service appointment with your dealer for repairs to be completed free of charge (parts and labor). Parts are anticipated to be available first quarter of 2023.

**What should you do?** When parts are available, Ford Motor Company will send a letter to inform you that parts are available and to contact your dealer to schedule a repair. Ford has not issued instructions to stop driving your vehicle under this safety recall. When parts are available, you should contact your dealer for an appointment to have your vehicle remedied as soon as practicable. You can continue to safely drive your vehicle.

If you do not already have a servicing dealer, you can access [ford.com/support](https://ford.com/support) for dealer addresses, maps, and driving instructions.

If you are still having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to [NHTSA.gov](https://www.nhtsa.gov). Reference NHTSA Safety Recall 22V-731.

**Please note: Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.**

Thank you for your attention to this important matter.

Ford Customer Service Division



Ford Motor Company  
División de Servicio al Cliente de Ford  
P. O. Box 1904  
Dearborn, Michigan 48121



771688040126

A/2/000001/1

Octubre de 2022



JOHN A. SAMPLE  
123 SAMPLE ST  
SAMPLE CITY, MI 12345-6789

## **\*\*\* CAMPAÑA DE SEGURIDAD IMPORTANTE \*\*\***

### **Aviso de Campaña 22S62 / Campaña 22V-731 de la NHTSA**

2021 Motorhome Chassis

Número de identificación del vehículo (VIN): XXXXXXXXXX

Este aviso se le envía de acuerdo con la Ley Nacional de Seguridad de Tránsito y Vehículos Motorizados de los EE. UU.

Ford Motor Company ha determinado que existe un defecto relacionado con la seguridad de su vehículo, con el VIN que aparece más arriba.

Lamentamos esta situación y deseamos asegurarle que, con su ayuda, corregiremos el problema. Nuestro compromiso, junto con el de su distribuidor, es ofrecerle servicio y apoyo de alto nivel.

#### **¿Cuál es el problema?**

El o los soportes de unión de la barra estabilizadora trasera de su vehículo podrían romperse y separarse del vehículo durante el uso.

#### **¿Qué riesgo existe?**

Si el o los soportes de unión de la barra estabilizadora trasera de su vehículo se rompen o se separan del vehículo, el conductor no experimentará un cambio repentino en la dinámica del vehículo y este permanecerá estable. No obstante, una separación del soporte de unión mientras conduce puede crear un potencial peligro para los otros usuarios del camino, lo cual aumenta el riesgo de choque.

#### **¿Qué medidas adoptarán Ford y su distribuidor?**

Ford Motor Company colabora estrechamente con sus proveedores para fabricar las piezas para esta reparación. Cuando estas estén disponibles, Ford Motor Company le avisará mediante correo para programar una cita de servicio con su distribuidor y así realizar las reparaciones sin costo alguno (piezas y mano de obra). Se prevé que las piezas estarán disponibles el primer trimestre de 2023.

#### **¿Qué debe hacer?**

Cuando las piezas estén disponibles, Ford Motor Company le enviará una carta para informarle la disponibilidad de estas y solicitarle que se comunique con su distribuidor a fin de programar la reparación.

Para esta campaña de seguridad, Ford no ha emitido instrucciones de no manejar el vehículo. Cuando las piezas se encuentren disponibles, deberá ponerse en contacto con su distribuidor a fin de programar una cita para solucionar este problema lo más pronto posible. Puede continuar manejando su vehículo con seguridad.

Si aún no tiene un distribuidor para realizar el servicio, puede acceder a [ford.com/support](https://ford.com/support) para conocer las direcciones de los distribuidores, ver mapas y obtener las instrucciones para llegar.

Si continúa con dificultades para reparar su vehículo en un tiempo razonable o sin cargo, le sugerimos que escriba al Administrador, National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E., Washington, D.C. 20590 o bien que llame sin cargo a la línea directa de seguridad vehicular al 1-888-327-4236 (TTY: 1-800-424-9153) o visite [NHTSA.gov](https://www.nhtsa.gov). Referencia: Campaña de seguridad 22V-731 de la NHTSA.

**Tenga presente que: La ley federal exige que los arrendadores de vehículos que reciban este aviso de campaña envíen una copia del mismo al arrendatario en un plazo de diez días.**

Gracias por su atención en este asunto sumamente importante.

Ford, División de Servicio al Cliente