

N720 H412 SAFETY RECALL – SEAT BELT RETRACTOR FUNCTIONALITY



SAFETY RECALL N720 H412 - SEAT BELT RETRACTOR FUNCTIONALITY

AFFECTED MODELS	22-23MY F-PACE, F-TYPE, and XF 22-23MY RR Velar, RR Sport, Discovery Sport, Discovery, and Defender
VOLUME AFFECTED	H412 USA 176 H412 Canada 113 N720 USA 4,927 N720 Canada 645
REPAIR	The front seat belt pretensioner tube may have been damaged during the manufacturing process. Less than 1% of vehicles are expected to have defective parts. Retailers will inspect the seat belt pretensioner tube for damage and if damage is identified, following instructions in the bulletin, will replace any defective parts.
REPAIR TIME	Inspect between 0.3 and 1.1 hrs. Inspect and Repair between 0.5 and 1.4 hrs + DIDO
CAMPAIGN LAUNCH	Retailer Notification only was issued August 4 th , 2022. N720 - NAS22.08.005 USA NAS22.08.006 CAN H412 - NAS22.08.003 USA NAS22.08.004 CAN Repair bulletin target publication date is August 15 th , 2022
Notes	For sold cars, customers will be notified by direct mail following the normal Recall process.