

H404 SAFETY RECALL – Incorrect Specification Tail Lamps



SAFETY RECALL H404 – Incorrect Specification Tail Lamps

AFFECTED MODELS	21-22MY F-PACE
VOLUME AFFECTED	USA 5,326 Canada 699
REPAIR	The rear tail lamps may not be to specification. Retailers will inspect rear tail lamp operation and where an incorrect specification tail lamp has been installed, following instructions in the bulletin, will replace with correct parts.
REPAIR TIME	Between 0.1 hrs for inspection and up to 0.4 hrs for repair + DIDO
CAMPAIGN LAUNCH	August 17th , 2022
Notes	The recall repair bulletin has been published to TOPIx. There are 6 affected vehicles in dealer inventory that need to be rectified before sale. <1% of vehicles are expected to fail inspection and require a new part.