

March 9, 2023

Ms. Briana Green Senior Corporate Counsel Xos, Inc. 3550 Tyburn St. Los Angeles, CA 90065

Subject: Driveshaft Separation

Dear Ms. Green:

This letter serves to acknowledge Xos, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

XOS/RM01/2021 XOS/SA01/2021 XOS/SV05/2021-2022

Mfr's Report Date: March 3, 2023

NHTSA Campaign Number: 23V-145

Components:

POWER TRAIN: DRIVELINE: DRIVESHAFT

Potential Number of Units Affected: 275

Problem Description:

Xos, Inc. (Xos) is recalling certain 2021 RM01, SA01, and 2021-2022 SV05 vehicles. The bolts connecting the electronic parking brake rotor to the driveshaft may have been improperly tightened.

Consequence:

Loose bolts may allow the driveshaft to separate, causing a loss of drive power and increasing the risk of a crash.

Remedy:

Dealers will replace the bolts and related hardware, free of charge. Owner notification letters are expected to be mailed March 28, 2023. Owners may contact Xos customer service at 1-888-316-1890. Xos's number for this recall is REC 002-23.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107SS 23V-145

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Xos, Inc.'s contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Alae Andy

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

