



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 26, 2023

Mr. Cole Stutz
Hyundai Motor America
10550 Talbert Avenue
Fountain Valley, CA 92708

NEF-107ES
23V-651

Subject: ABS Unit May Cause Engine Compartment Fire

Dear Mr. Stutz:

This letter serves to acknowledge Hyundai Motor America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/ACCENT/2012-2015
HYUNDAI/AZERA/2012-2015
HYUNDAI/ELANTRA/2011-2015
HYUNDAI/ELANTRA COUPE/2013-2015
HYUNDAI/EQUUS/2014-2015
HYUNDAI/GENESIS COUPE/2011-2015
HYUNDAI/SANTA FE/2013-2015
HYUNDAI/SANTA FE SPORT/2013
HYUNDAI/SONATA HYBRID/2011-2015
HYUNDAI/TUCSON/2010-2013
HYUNDAI/TUCSON FUEL CELL/2015
HYUNDAI/VELOSTER/2012-2015
HYUNDAI/VERACRUZ/2010-2012

Mfr's Report Date: September 22, 2023

NHTSA Campaign Number: 23V-651

Components:

SERVICE BRAKES, HYDRAULIC:ANTILOCK/TRACTION CONTROL/ELECTRONIC LIMITED
SLIP:CONTROL UNIT/MODULE

Potential Number of Units Affected: 1,642,551

Problem Description:

Hyundai Motor America (Hyundai) is recalling certain 2011-2015 Elantra, Genesis Coupe, Sonata Hybrid, 2012-2015 Accent, Azera, Veloster, 2013-2015 Elantra Coupe, Santa Fe, 2014-2015 Equus, 2010-2012 Veracruz, 2010-2013 Tucson, 2015 Tucson Fuel Cell, and 2013 Santa Fe Sport vehicles. The Anti-Lock Brake System (ABS) module may leak brake fluid internally and cause an electrical short, which can result in an engine compartment fire while parked or driving.

Consequence:

An engine compartment fire while parked or driving can increase the risk of injury.



Remedy:

Owners are advised to park outside and away from structures until the recall repair is complete. Dealers will replace the ABS fuse, free of charge. Owner notification letters are expected to be mailed November 21, 2023. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 251.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Hyundai Motor America's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement