

# Recall Quarterly Report

## 23V-150

**Manufacturer Name :** Terex Advance Mixer, Inc.

**NHTSA Recall No. / MFR Recall No. :** 23V-150 /

**Recall Subject :** Steering Shaft May Separate from Steering Column

**Owner Notification Beginning Date :** MAY 22, 2023

**Owner Notification End Date:** MAY 22, 2023



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | OCT 02, 2023    | 2023-3         | 271               | 10             | 0                 | 0             |
| 1        | OCT 02, 2023    | 2023-2         | 271               | 10             | 0                 | 0             |

This Document Last Updated : OCT 03, 2023

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.