

Part 573 Safety Recall Report

23C-005

Manufacturer Name : Evenflo Company, Inc.

Submission Date : JAN 09, 2024

NHTSA Recall No. : 23C-005

Manufacturer Recall No. : N/a



Manufacturer Information :

Manufacturer Name : Evenflo Company, Inc.

Address : 225 BYERS ROAD
MIAMISBURG OH 45342

Company phone : 937-415-3300

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

Child Restraint Information :

Make 1 : Evenflo

Model : Titan 65

Seat Type : OTHER

Model No. : 3712198 PQ1

Platform Name / No. : NR

Brand Name : Evenflo

Descriptive Information : The population consists of a single unit reported, and subsequently verified, as being manufactured and shipped with a required warning label missing.

There is no indication of other units in the population consisting of contemporaneously manufactured product exhibiting the same non-compliance, for which 100% inspection was performed as part of the manufacturing process.

Production Dates : MAY 20, 2022 - MAY 20, 2022

Description of Noncompliance :

Description of the Noncompliance : The subject unit was manufactured and shipped without the warning label required pursuant to FMVSS 213, S5.5

FMVSS 1 : 213 - Child restraint systems

FMVSS 2 : NR

Description of the Safety Risk : A consumer using the product would not have immediate access to the information required to be included on the label. This presents a potential for increased injury risk, to the extent a consumer does not receive warning and;/or safety information included on the label.

Description of the Cause : Error in the manufacturing process (both with respect to application of the label and inspection for its presence).

Identification of Any Warning that can Occur : The absence of the label is readily visible.

Involved Components :

Component Name : Warning Label

Component Description : Label affixed to unit to comply with FMVSS 213 S5.5

Component Part Number : 25809076

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

May 20, 2022 - Date of manufacture of the relevant car seat.

September 12, 2023 - Report received indicating that the relevant car seat did not have the appropriate warning label.

October 30, 2023 - The car seat, having been retrieved, was inspected. The absence of a warning label was confirmed. No adhesive residue was apparent. On that basis, it was concluded that no label was affixed during the manufacturing process and, accordingly, the unit as shipped was noncompliant.

Description of Remedy :

Description of Remedy Program : The affected unit was retrieved for inspection and is in the possession the manufacturer. The retrieved unit will be destroyed. There is no (current) field population requiring remedy.

How Remedy Component Differs from Recalled Component : Not applicable

Identify How/When Recall Condition was Corrected in Production : Evenflo has no indication that other units produced in the relevant time frame exhibited the non-compliance, which reflected an individual production error. However, coincidentally (i.e., unrelated to this incident), production processes starting on May 23, 2023 were updated to include 100% inspection for the label. On November 11, 2022 the production process was further improved to include automated QR Code scanning for the presence of the label.

Recall Schedule :

Description of Recall Schedule : As noted above, there is no affected population (currently) in the field and therefore no recall will be performed.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported