

Part 573 Safety Recall Report

23E-098

Manufacturer Name : Villa International**Submission Date :** JAN 04, 2024**NHTSA Recall No. :** 23E-098**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Villa International**Address :** 13760 Midway Street
Cerritos CA 90703**Company phone :** 888-707-7272**Population :****Number of potentially involved :** 35**Estimated percentage with defect :** 1 %**Equipment Information :****Brand / Trade 1 :** Villa**Model :** pedestal 400004**Part No. :** 400004**Size :** NR**Function :** NR**Descriptive Information :** the recall population is determined from the pedestal lot number of 04/19/2023 of which it the defective pedestal was 1 out of 35 pedestals in that lot.**Production Dates :** APR 19, 2023 - APR 19, 2023**Brand / Trade 2 :** Villa**Model :** pedestal 400004**Part No. :** 400004**Size :** NR**Function :** seat anchorage**Descriptive Information :** The recall population was determined from the pedestal lot date of 04/19/22 of which the defective pedestal was 1 out of 35 fabricated that day.**Production Dates :** APR 19, 2022 - APR 19, 2022**Description of Defect :****Description of the Defect :** The pedestal can to mounting plate is not properly welded.**FMVSS 1 :** 207 - Seating systems**FMVSS 2 :** 210 - Seat belt assembly anchorages**Description of the Safety Risk :** the can to mounting plate could separate.

Description of the Cause : The can to mounting plate is not properly welded.

Identification of Any Warning that can Occur : The seat assembly will be loose.

Involved Components :

Component Name : pedestal

Component Description : seating pedestal

Component Part Number : 400004

Supplier Identification :

Component Manufacturer

Name : villa

Address : 4733 eastland dr
Elkhart Indiana 46516

Country : United States

Chronology :

The vehicle manufacturer notified Villa International via a supplier corrective action report dated 12.15.23. The Unit numbers of the vehicles that may have a seat with a defective pedestal were submitted to Newmar. 12.22.23

Description of Remedy :

Description of Remedy Program : compile a listing of seats affected by the pedestals from the lot of 35. The suspect pedestals can be visually inspected for the missing weld, allowing .10 hr. The repair will include replacement of the defective pedestal allowing 1 hr time .

How Remedy Component Differs from Recalled Component : The replacement pedestal will have the proper welds.

Identify How/When Recall Condition was Corrected in Production : There are separate staging area for pedestals that are not welded vs completed pedestals prior to powder coating..

Recall Schedule :

Description of Recall Schedule : The vehicle manufacturer notified 12.22.23 of possible vehicles that may have a defective pedestal.
Planned Dealer Notification Date : JAN 09, 2024 - MAR 09, 2024
Planned Owner Notification Date : JAN 09, 2024 - MAR 09, 2024

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Newmar
Address : 356 N. Delaware St.
Nappanee IN 46550
Country : US
Company Phone : 574 7737791

* NR - Not Reported