

# Part 573 Safety Recall Report

## 23V-150

**Manufacturer Name :** Terex Advance Mixer, Inc.**Submission Date :** MAR 07, 2023**NHTSA Recall No. :** 23V-150**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Terex Advance Mixer, Inc.

Number of potentially involved : NR

Address : 7727 Freedom Way  
Fort Wayne IN 46818

Estimated percentage with defect : NR

Company phone : 999

**Vehicle Information :**

Vehicle 1 : 2022-2023 Front Discharge Mixer Commander &amp; Charger

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Terex Advance Mixer received a call from a customer stating they had lost steering control. After investigation it was determined that the steering shaft had come loose from the steering column and resulted in a loss of steering.  
There were no injuries or property damage as a result of this event.

Production Dates : NOV 01, 2022 - FEB 28, 2023

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : Vehicles within the subject population may be affected by the improper installation/torquing of the steering shaft to the steering column.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loss of steering control may result in loss of vehicle control and property damage and an increased risk of a crash.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

Feb. 16, 2023 - Terex Advance Mixer received a call from a customer stating they lost control of the vehicle.

Feb. 20, 2023 - Terex started an internal investigation to determine root cause of the issue experienced by the vehicle in question, and if that issue might impact a larger population of Terex Advance Mixers. personnel visited the customer location to evaluate the issue.

Mar 3, 2023 - Based on our internal investigation we determined that there could possibly be installation/torque issues associated with the steering shaft. Out of an abundance of caution we determine that a recall is necessary.

Mar 7, 2023 - Terex Advance Mixer filed a 573 Defect Report

### Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs  
from Recalled Component :

Identify How/When Recall Condition  
was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported