Part 573 Safety Recall Report

23V-368

Manufacturer Name: Fontaine Trailer Company

Submission Date: MAY 25, 2023 NHTSA Recall No.: 23V-368 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Fontaine Trailer Company

Address: 430 Letson Industrial Road

Haleyville AL 35565

Company phone: 800-821-6535

Population:

Number of potentially involved : 545Estimated percentage with defect : 100%

Vehicle Information:

Vehicle 1: 2023-2024 Fontaine HACCFON51CTS

Vehicle Type: TRAILERS
Body Style: OTHER
Power Train: NR

Descriptive Information: The recall population includes all 40 ft container chassis of the model listed (873

units) less the units that were still at our facility that were updated to be in compliance with FMVSS 108 (328 units) leaving 545 units to be recalled and

corrected.

Production Dates: AUG 22, 2022 - APR 13, 2023

VIN Range 1: Begin: 13NJ412A5P1560357 End: 13NJ412A0P1560606 ☐ Not sequential VIN Range 2 : Begin : 13NJ412A6R1560676 End: 13NJ412A0R1560754 ■ Not sequential VIN Range 3: Begin: 13NJ412A4R1560756 End: 13NJ412A5R1560765 Not sequential VIN Range 4: Begin: 13NJ412AXR1560776 End: 13NJ412A1R1560780 Not sequential VIN Range 5: Begin: 13NJ412A0R1560821 End: 13NJ412A8R1560825 Not sequential VIN Range 6: Begin: 13NJ412A3R1560845 End: 13NJ412A1R1560925 Not sequential VIN Range 7: Begin: 13NJ412AXR1564133 End: 13NJ412AXR1564147 ☐ Not sequential VIN Range 8: Begin: 13NJ412A9R1564172 End: 13NJ412A0R1564271 Not sequential

Description of Noncompliance:

Description of the The red Reflex Reflectors located on the rear of the chassis as far apart as

Noncompliance: practicable per FMVSS 108 Table 1-B were omitted during production. The red

Reflex Reflectors located on the side as far to the rear as practicable per FMVSS

108 Table 1B may have also been omitted on some units.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: The missing red Reflex Reflectors are a requirement under FMVSS 108. As a

Description of the Safety Risk: result, the trailers in question are currently out of compliance with the

Description of the Cause: The red Reflex Reflectors located at the rear of the chassis were not installed

during production as required per FMVSS 108 requirements.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

During a Sales Call in April involving a walk-around of a recent production 40 ft Chassis with a potential new Customer, it was brought to Fontaine's attention that the unit may not be in compliance with FMVSS 108 Reflector requirements. Subsequent review of "like" units located at the Fontaine facility confirmed that the red Reflex Reflectors on the rear corners had been omitted during production of the units.

Description of Remedy:

Description of Remedy Program: Fontaine will supply all affected customers with 4 red Reflex Reflectors per

unit to correct the units in their possession. Fontaine will cover all costs

associated with making the vehicles compliant per FMVSS 108

requirements.

from Recalled Component: during production.

How Remedy Component Differs The remedy will involve installing red Reflex Reflectors that were omitted

Identify How/When Recall Condition The production personnel, quality personnel and Production Supervisors was Corrected in Production: were re-trained on FMVSS 108 requirements to prevent future mishaps.

Recall Schedule:

Description of Recall Schedule: Fontaine will solicit the customer sites that need to have product

provided and will supply needed product in quantities adequate to

service the customer sites. Fontaine has inventory on hand to service the

affected units.

Planned Dealer Notification Date : MAY 30, 2023 - JUN 02, 2023 Planned Owner Notification Date : JUN 05, 2023 - JUN 16, 2023

^{*} NR - Not Reported