

Part 573 Safety Recall Report

23V-522

Manufacturer Name : Airstream, Inc.**Submission Date :** JUL 27, 2023**NHTSA Recall No. :** 23V-522**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Airstream, Inc.

Address : 419 West Pike Street
 PO Box 629 Jackson Center OH
 45334-0629

Company phone : 937-596-6111**Population :****Number of potentially involved :** 19**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2019-2023 Creative Mobile Interiors Upfitted Units**Vehicle Type :****Body Style :** UNKNOWN**Power Train :** NR

Descriptive Information : The supplier Cummins provided a list of the affected generators to Creative Mobile Interiors, CMI in turn compiled a list of upfitted RVs the affected generators were used in and provided that to Airstream. Airstream used that information to set our recall scope.

Production Dates : APR 17, 2018 - APR 21, 2023**VIN Range 1 : Begin :** NR**End :** NR☐ Not sequential**Description of Defect :**

Description of the Defect : Per Cummins Recall 23E030; "The fuel hose between the inline fuel filter and the injection pump module (IMP) may have inadequate clamp force, possibly resulting in a gasoline leak."

FMVSS 1 : NR**FMVSS 2 :** NR

Description of the Safety Risk : Per Cummins Recall 23E030; "A gasoline leak in the presents of an ignition source may increase the risk of fire". This could result in personal injury.

Description of the Cause : Per Cummins Recall 23E030; "The cause of the issue is an inadequate specification of the fuel hose."

Identification of Any Warning that can Occur : Per Cummins Recall 23E030 "Bystanders may see or smell gasoline."

Involved Components :

Component Name 1 : Fuel Line

Component Description : Fuel Line

Component Part Number : A073T925

Supplier Identification :

Component Manufacturer

Name : Cummins Inc.

Address : 4000 Lyman Drive
Hilliard Ohio 43026

Country : United States

Chronology :

7/17/23 - Airstream received information from Creative Mobile Interiors (Airstream acquired CMI in early in 2023) regarding a notification from NHTSA stating that they were identified by Cummins as a purchaser of subject equipment involved in NHTSA recall 23E030. 7/18/2023 CMI provided Airstream with a list of their retail owners with the affected Onan generators. 7/25/23 - Airstream received a directive from THOR Compliance stating that they have had conversation with NHSTA, and it was decided that a separate 573 should be submitted by Airstream for the units upfitted by CMI.

Description of Remedy :

Description of Remedy Program : Per Cummins Recall 23E030; "The remedy is to inspect and, if the unit has the defect, to replace the subject fuel hose and associated clamps. A recall-specific reimbursement plan will be provided on the Recall Portal for those units not covered by the manufacturer's limited warranty." Customers will be allowed reimbursement following the general reimbursement plan on file with NHTSA

How Remedy Component Differs from Recalled Component : Per Cummins Recall 23E030; "The remedy fuel hose has a unique part number A073T925." The units will be visually the same to the end user.

Identify How/When Recall Condition was Corrected in Production : Per Cummins Recall 23E030; "Production began with the remedy fuel hose on 02/21/2023."

Recall Schedule :

Description of Recall Schedule : Airstream will send dealer and owner notification letters once approved by NHTSA.

Planned Dealer Notification Date : SEP 25, 2023 - SEP 25, 2023

Planned Owner Notification Date : SEP 25, 2023 - SEP 25, 2023

* NR - Not Reported