Part 573 Safety Recall Report

Manufacturer Name :Daimler Trucks North America, LLCSubmission Date :SEP 01, 2023NHTSA Recall No. :23V-537Manufacturer Recall No. :FL980



Number of potentially involved : 205 Estimated percentage with defect : 1 %

Population :

23V-537

Manufacturer Information :

Manufacturer Name :Daimler Trucks North America, LLCAddress :4747 N. Channel AvenuePortland OR 97217-3849800-745-8000

Vehicle Information :

Vehicle 1:	2023-2023 Freightliner M2
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES
Body Style :	2-DOOR
Power Train :	DIESEL
Descriptive Information :	Certain trucks built with drive shafts manufactured with components supplied by Dana with non-conforming material from two specific production lots. Population is based on updated information from DANA (supplier) and Grimaldi, a 3rd party component sequencer.
Production Dates :	SEP 13, 2022 - OCT 11, 2022
VIN Range 1:	Begin : NR End : NR Not sequential

Description of Defect :

Description of the Defect :	From the suppliers defect report, "supplier's use of non-conforming material in its production processes, the specified drive shafts do not meet specification and can break in certain high loading conditions".
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	From supplier defect report, "in the event a driveshaft breaks, it can separate from the vehicle, which could increase the risk of a crash".
Description of the Cause :	Due to an error in the supplier's production processes, non-conforming material was used to manufacture the specified driveshafts.
Identification of Any Warning that can Occur :	

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Component Name 1 : Drive Shaft Component Description : Drive Shaft Component Part Number : SPL 100

Supplier Identification :

Component Manufacturer

Name : Dana-Spicer Address : 3939 Technology Drive Maumee Ohio 43537 Country : United States

Chronology :

On July 26, 2023, DTNA received a copy of the Defect Information Report that Dana filed a recall for a certain lot of potentially defective drive shafts after completing an analysis of a single drive shaft failure in April of 2023. After reviewing preliminary information furnished from Dana, DTNA was able to match a suspect population range. On July 31, 2023, DTNA decided to file a vehicle companion recall to support Dana's recall for this issue. DTNA is not aware of any accidents or injuries related to this issue. DTNA anticipates the recall population may be adjusted after receiving additional information from Dana cross-referencing part serial number to truck VINs. DTNA found1 total warranty claims related to this issue. On August 30, 2023, DTNA was provided with updated population information from Dana. Dana's records indicated the suspect parts were shipped to Grimaldi, a 3rd party sequencer, who assigns a specific, serialized number part to a truck VIN. Based on this updated population information from Dana, DTNA was able to refine the vehicle population following a comprehensive review of the documentation of suspect serialized driveshafts shipped from Dana to Grimaldi.

Description of Remedy :

Description of Remedy Program :	Affected vehicle owners will receive a replacement drive shaft. DTNA is currently developing the repair strategy. Repairs will be performed free of charge by Daimler Truck North America authorized service facilities. Details of the reimbursement plan will be included in the owner's notification letter. Owners are directed to seek reimbursement through authorized dealers.
How Remedy Component Differs from Recalled Component :	

23V-537

The information contained in this report was submitted pursuant to 49 CFR §573

	Based on information provided by the supplier, the issue was cause by a sub-supplier's use of nonconforming material, which has since been corrected in production.
Recall Schedule :	
	Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customers affected
	Trucks North America records to determine the customers affected.

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573