

Part 573 Safety Recall Report

23V-637

Manufacturer Name : Winnebago Industries, Inc.

Submission Date : MAR 20, 2024

NHTSA Recall No. : 23V-637

Manufacturer Recall No. : 177



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 5,369

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2022-2022 Winnebago Ekko

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying units built within the time frame of an internal rework campaign where Hitch Load Rating labels were reviewed. Units built after this internal campaign were determined to be correct.

Production Dates : APR 15, 2021 - APR 15, 2021

VIN Range 1 : Begin : NR **End :** NR

☐ Not sequential

Vehicle 2 : 2020-2022 Winnebago Minnie Winnie / Spirit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying units built within the time frame of an internal rework campaign where Hitch Load Rating labels were reviewed. Units built after this internal campaign were determined to be correct.

Production Dates : SEP 28, 2018 - JUL 27, 2021

VIN Range 1 : Begin : NR **End :** NR

☐ Not sequential

Vehicle 3 : 2020-2022 Winnebago View / Navion

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying units built within the time frame of an internal rework campaign where Hitch Load Rating labels were reviewed. Units built after this internal campaign were determined to be correct.

Production Dates : MAR 01, 2019 - AUG 05, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2020-2021 Winnebago Vita / Porto

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying units built within the time frame of an internal rework campaign where Hitch Load Rating labels were reviewed. Units built after this internal campaign were determined to be correct.

Production Dates : SEP 10, 2018 - JUN 28, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : An incorrect hitch label was installed.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An incorrect hitch label could lead to incorrect loading of the vehicle, increasing the risk of a crash.

Description of the Cause : Operator installed the incorrect label

Identification of Any Warning that can Occur : No warning

Involved Components :

Component Name 1 : Hitch Label

Component Description : Hitch Label

Component Part Number : 172243

Component Name 2 : Hitch Label

Component Description : Hitch Label

Component Part Number : 315722

Component Name 3 : Hitch Label

Component Description : Hitch Label

Component Part Number : 129669

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

A customer called in to advise the hitch load label on their unit as incorrect. After an investigation, the customer unit was found to be part of a population previously identified in an internal quality campaign. Further review of units produced after the internal campaign were verified to be correct. The Product Safety Committee met on September 7, 2023 and decided to conduct a voluntary recall.

Winnebago is aware of 1 reported incident related to the recall condition, first becoming aware on or about May 2023. Of this incident, we are aware of 0 injuries.

Description of Remedy :

Description of Remedy Program : Winnebago will coordinate sending the correct labels for installation on the affected units.

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : The remedy component will be the correct called out label as originally specified.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production through the action of an internal quality campaign and operator training.

Recall Schedule :

Description of Recall Schedule : The recall schedule will follow the 60 day requirement
Planned Dealer Notification Date : SEP 22, 2023 - SEP 22, 2023
Planned Owner Notification Date : APR 12, 2024 - APR 12, 2024

* NR - Not Reported