

Part 573 Safety Recall Report

23V-871

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** DEC 21, 2023**NHTSA Recall No. :** 23V-871**Manufacturer Recall No. :** N830**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 4,347

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2023-2023 Land Rover Range Rover Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2023MY Land Rover Range Rover Sport vehicles built at the Solihull Vehicle Assembly Plant from July 1, 2022 - November 30, 2022. 4347 vehicles in the United States and Federalized Territories.

The recall population was established based on the elevated pattern and trend of reports of righthand tail lamp failures coupled with dates where the finessing processes were employed.

Production Dates : JUL 01, 2022 - NOV 30, 2022

VIN Range 1 : Begin : SAL1L9FU1PA100681 End : SAL1P9EU1PA113677 Not sequential**Description of Defect :**

Description of the Defect : A concern has been identified with the right hand tailgate and body mounted rear lamps which may experience water ingress leading to one or more lamp failures including loss of brake/stop lamp, outer marker lamp, reversing lamp and direction indicator/turn indicator.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Loss of rear right hand lamp system functionality increases the risk of a rear end collision.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : BODY SIDE LAMP TAILGATE LAMP

Component Description : BODY SIDE LAMP TAILGATE LAMP

Component Part Number : N9X2 - 13404 - A/B

Component Name 2 : BODY SIDE LAMP TAILGATE LAMP

Component Description : BODY SIDE LAMP TAILGATE LAMP

Component Part Number : N9X2 - 13405 - A/B

Component Name 3 : BODY SIDE LAMP TAILGATE LAMP

Component Description : BODY SIDE LAMP TAILGATE LAMP

Component Part Number : N9X2 - 13A420 - A/B

Component Name 4 : BODY SIDE LAMP TAILGATE LAMP

Component Description : BODY SIDE LAMP TAILGATE LAMP

Component Part Number : N9X2 - 13A421 - A/B

Supplier Identification :

Component Manufacturer

Name : Jaguar Land Rover Limited

Address : Abbey Road

Whitley Coventry Foreign States CV3 4LF

Country : United Kingdom

Chronology :

Attached file

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Jaguar Land Rover repairer. The right hand tailgate and body mounted lamps will be replaced. Until such time as the recall has been completed, customers are advised to regularly check the operation of their rear lamps and if they fail to function as expected or differ from the operation the left hand side, seek retailer assistance. There will be no charge to the owners for this repair. The affected vehicles will be covered under Jaguar Land Rover's new vehicle warranty program. Therefore, reimbursement for pre-notice remedies are not necessary because the affected vehicles are still under warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer notification is planned January 4, 2024. Owner notification is planned on or before February 9, 2024

Planned Dealer Notification Date : JAN 04, 2024 - JAN 04, 2024

Planned Owner Notification Date : FEB 09, 2024 - FEB 09, 2024

* NR - Not Reported