



Stacy L. Balzer
 Operating Director
 Service Engineering Operations
 Ford Customer Service Division

Ford Motor Company
 P. O. Box 1904
 Dearborn, Michigan 48121

March 13, 2023

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice - Safety Recall 23S06 – Supplement #2**
 Certain 2022-2023 Model Year Bronco, Explorer, F-150, Mustang and 2023 Aviator Vehicles Equipped With 10 Speed Automatic Transmission Transmission Assembly Inspection

REF: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice - Safety Recall 23S06 - Supplement #1**
 Dated: February 28, 2023

New! REASON FOR THIS SUPPLEMENT

- **Affected Vehicles:** Additional vehicles have been identified as affected by this inspection process, increasing the total population and affected build date ranges. All affected vehicles are identified in OASIS and FSA VIN lists.

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
F150	2022-2023	Dearborn	09-Nov-2022 through 19-Jan-2023
F150	2022-2023	Kansas City	18-Nov-2022 through 19-Jan-2023
Mustang	2022-2023	Flat Rock	01-Dec-2022 through 19-Jan-2023
Aviator	2023	Chicago	15-Nov-2022 through 26-Jan-2023
Explorer	2022-2023	Chicago	13-Nov-2022 through 28-Jan-2023
Bronco	2022-2023	Michigan	14-Nov-2022 through 09-Feb-2023

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

In some of the affected vehicles, the transmission may contain a loose (extra) bolt introduced during the transmission assembly process quality review. A loose bolt inside the transmission could prevent the transmission from achieving park by blocking the park pawl from engaging the park gear, although the gear shifter position may indicate that the vehicle has been shifted to "PARK." Loss of the ability to secure the park pawl could result in unintended vehicle movement, increasing the risk of a crash or injury.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers in the second quarter of 2023, when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$26,315 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting, or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,



Stacy L. Balzer