


SERVICE PROCEDURE

23508
APRIL 2023

SUBJECT: SAFETY RECALL INTERIM NOTICE
Intellipark Tractor Park Valve Module (PVM) on
certain 2023 HV®, HX®, LoneStar®, LT®, and RH®
series trucks built 05/18/2022 thru 08/05/2023 with
feature code 04GBN – (Electronic Park Brake) for
Tractor or Truck with Trailer Applications



DEFECT DESCRIPTION

The Intellipark Tractor Park Valve Module (PVM) may intermittently become stuck in the un-parked position and not set the park brake when the park brake switch is pulled on the vehicle dashboard. If a driver does detect the Intellipark PVM malfunction indications and does not properly fan down the service brakes, the vehicle may unintentionally move which increases the likelihood of a crash that may result in property damage or personal injury.

MODELS INVOLVED

This safety recall involves certain 2023 HV®, HX®, LoneStar®, LT®, and RH® series trucks built 05/18/2022 thru 08/05/2023 with feature code 04GBN – (Electronic Park Brake) for Tractor or Truck with Trailer Applications.

ELIGIBILITY

This procedure applies ONLY to vehicles marked in the Navistar Service Portal with safety recall 23508.

PARTS INFORMATION

This interim service procedure requires no parts.

ACTIONS YOU SHOULD TAKE

Advise your customers and other people that may be driving one of these vehicles to follow these procedures until the vehicle has had the final remedy installed on the vehicle. To minimize the potential risk of this defect in the interim period, please assume the parking brake does not set when the park brake switch is pulled; turn the ignition to Key OFF position, repeatedly apply the

service brake to evacuate the air supply until low system pressure sets the park brakes.

Should a customer call regarding this recall, please ensure they understand the same "Actions You Should Take", written in their interim notice.

A final remedy is expected to be available summer 2023.

NAVISTAR, INC.

