



RECALL 01A, Z46, OR Z96 - 3.0L ENGINE HIGH-PRESSURE FUEL PUMP REPAIR

If you have customer in for service with a 3.0L engine affected by recall 01A, Z46, or Z96, and the repair requires a high-pressure fuel pump, it is appropriate to use current service parts in the repair.

PN 68501449AA (old HPFP) has superseded to PN 68631088AA (new). Additionally, some orders for the new part number (PN 68631088AA) have been filled using the campaign kit PN CSSMZ461AA. If you have received PN CSSMZ461AA it can be used as a current service part.

The customer should NOT be charged for the repair. Submit a warranty claim in RA status with the proper details for approval and payment.

If you have any questions, please reach out to your tech advisor/area manager directly.

