



Stacy L. Balzer
Operating Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

June 14, 2023

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice - Compliance Recall 23C14 – Supplement #1**
Certain 2020-2023 Model Year Police Interceptor Utility Vehicles Equipped with a 12.1-inch Integrated Computer Screen (ICP)
ICP Software Update

REF: **NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice - Compliance Recall 23C14**
Dated May 1, 2023

New! REASON FOR THIS SUPPLEMENT

- **Affected Vehicles:** Additional vehicles have been added to the vehicle population. Model year and build dates have been updated to reflect the increase in population.
- **Service Action:** Software is anticipated to be available by July 31, 2023.

New! AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
Police Interceptor Utility	2020- <i>2023</i>	Chicago	June 26, 2020, through <i>April 26, 2023</i>

US population of affected vehicle: *521*. Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS COMPLIANCE RECALL

The affected vehicles do not conform to the requirements specified by Federal Motor Vehicle Safety Standard (FMVSS) No. 111 Sections 5.5.3 Response Time and 5.5.6 Default View. When the customer turns the Display On/Off button to “off” prior to placing the vehicle in reverse, the backup camera image will not appear on the display.

NEW! SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this compliance recall. A complete Dealer Bulletin will be provided to dealers by *July 31, 2023*, when it is anticipated that software information and repair instructions will be available to support this compliance recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

CUSTOMER NOTIFICATION

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$26,315 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

A handwritten signature in black ink that reads "Stacy L. Balzer". The signature is written in a cursive, flowing style.

Stacy L. Balzer