

# ***SERVICE PROCEDURE***

23514  
July, 2023

**SUBJECT: SAFETY RECALL**  
**Back-up Lamps on certain 2001 thru 2003 International® 9100i model trucks built 11/16/2000 thru 09/23/2002, 2004 thru 2009 International® 9200i model trucks built 06/26/2003 thru 05/15/2008, 2009, 2011, 2012, 2017 International® ProStar® model trucks built 07/22/2008 thru 10/08/2008, 08/11/2010 thru 11/16/2011, and 06/06/2016 thru 09/06/2016 and 2021 International® RH™ Series trucks built 06/03/2020 thru 09/08/2020 with feature code 01WPN, 01WPS, or 01VAL (pintle hook, includes mounting bracket for lowering pintle hook)**

## **CUSTOMER LETTER**

Print ready (PDF file) copy of the [Customer Letter](#)

## **DEFECT DESCRIPTION**

Certain trucks may not conform to Federal Motor Vehicle Safety Standard (FMVSS) 108 and/or Canada Motor Vehicle Safety Standard (CMVSS) 108 - If any required lamp or reflective device is obstructed by motor vehicle equipment, the vehicle must be equipped with an additional lamp or device of the same type. Specifically, Navistar did not equip these vehicles with additional unobstructed back-up lamps. Back-up lamps that do not conform to all the requirements of FMVSS 108 and/or CMVSS 108 while in bobtail mode and in reverse with obstructed back-up lamps may increase the risk of a vehicle crash.

## **MODELS INVOLVED**

Back-up Lamps on certain 2001 thru 2003 International® 9100i model trucks built 11/16/2000 thru 09/23/2002, 2004 thru 2009 International® 9200i model trucks built 06/26/2003 thru 05/15/2008, 2009, 2011, 2012, 2017 International® ProStar® model trucks built 07/22/2008 thru 10/08/2008, 08/11/2010 thru 11/16/2011, and 06/06/2016 thru 09/06/2016 and 2021 International® RH™ Series trucks built 06/03/2020 thru 09/08/2020 with feature code 01WPN, 01WPS, or 01VAL (pintle hook, includes mounting bracket for lowering pintle hook).

## **ELIGIBILITY**

This procedure applies ONLY to vehicles marked in the International® Service Portal<sup>SM</sup> with Safety Recall 23514.

## **PARTS INFORMATION**

This interim service procedure requires no parts.

## **ACTIONS YOU SHOULD TAKE**

Advise your customers and other people that may be driving one of these vehicles to minimize the potential risk of this noncompliance, the operator should exercise greater caution while in bobtail mode and in reverse. Their back-up lamp may not be completely visible to someone behind them.

Should a customer call regarding this recall, please ensure they understand the same “Actions You Should Take”, written in the interim notice they received in the mail.

Parts are expected to be available early August 2023.

**NAVISTAR, INC.**