

APA9 Recall campaign - Replacing screw connection for seat belt mount at rear left and/or right

APA9 Recall campaign - Replacing screw connection for seat belt mount at rear left and/or right

| | |
|-----------------------------|---|
| ID Number | APA9 |
| Models | Macan (95B) Panamera (971) |
| Model Years | 2015-2023 |
| VIN list | Attached |
| Number of Affected VINs | 37 |
| Issue Description | Due to an off-line assembly process deviation that has since been corrected, the lower rear outer seat belt anchors on the subject vehicles may not have been tightened to the correct specification. As a result, the lower seat belt anchors for the rear outer seats could come loose over time. |
| What should Dealers do? | Please arrange for customer vehicles to have the campaign carried out as soon as possible. As of the time of this posting (7/27/23) the repair is immediately available. Parts can be ordered via PPL as normal. |
| What will Porsche do? | The rear outer seat belt anchor bolts will be replaced. |
| TI Number | No. 99-23 |
| Customer letter | Will be posted at a later date. |
| Customer Reactive Statement | Our first priority is the safety of anyone travelling in one of our cars - this commitment leads to a culture of relentless checks. As part of this work, it was discovered that a rear outer seat belt anchor bolt on 37 Macan and Panamera vehicles may not have been tightened to the correct specification, and could, over ti- |

me, loosen. To remedy any vehicles that may have been affected, the seat belt anchor bolts will be replaced. No incidents attributed to this issue have been reported. Owners will be contacted proactively, and the work will be carried out free of charge.

Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement vehicle.

Please invoice this additional service via WWS with the campaign scope.

Required parts

| Part number | Designation | Quantity/vehicle scope-related | Parts return request |
|-------------|--|--------------------------------|----------------------|
| N 91209801 | Fastening screw | 1 to 2 | No |
| or | | | |
| N 91269501 | Oval-head screw with hexagon socket head | 1 to 2 | No |

Warranty processing

Please enter the campaign carried out in the Warranty and Maintenance Logbook for the vehicle.

Scope 1: Replacing rear left seat belt end fitting screw connection

- for Macan

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 45 TU |

Scope 2: Replacing rear right seat belt end fitting screw connection

- for Macan

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 45 TU |

Scope 3: Replacing rear left and right seat belt end fitting screw connection

- for Macan

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 48 TU |

Scope 4: Replacing rear left seat belt end fitting screw connection

- for Panamera

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 34 TU |

Scope 5: Replacing rear right seat belt end fitting screw connection

- for Panamera

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 34 TU |

Scope 6: Replacing rear left and right seat belt end fitting screw connection

- for Panamera

| | |
|-------------|-------------|
| Damage Code | APA9 99 000 |
| Repair Code | 2 |
| Labor time | 42 TU |

Attachments

1. [VIN_List_Report_APA9_2023-07-26_V2.xlsx](#)