

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Thomas Built Buses Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Detroit Diesel Distributors
Export Distributors

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNA Portal](#)

REF #: ICI24-021

Effective: 05/08/2024

Release: 05/08/2024

SUBJECT: FL979 – Revised Bulletin

This letter is to inform you that a revised bulletin for Recall FL979 Freightliner eCascadia e-Axle Ring Gear is available on DTNAPortal. Please print and use the revised bulletin for all work under FL979 from this point forward.

NEW REVISION: The Labor Allowance table has been revised due to incorrect application of SRTs to respective groups, resulting in the omission of time for road tests, alignments, or time required to paint the axles when necessary. Additionally, certain steps have been added to the work instructions, while others have been rearranged to enhance clarity.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC link on DTNAPortal.

REF #: ICI24-021

En vigueur: 08/05/2024

Date de sortie: 08/05/2024

OBJET: FL979 – Bulletin révisé

Cette lettre a pour but de vous informer qu'un bulletin révisé pour le rappel FL979 Engrenage annulaire Freightliner eCascadia à essieux E est disponible sur DTNAPortal. Veuillez imprimer et utiliser le bulletin révisé pour tous les travaux sous FL979 à partir de maintenant.

NOUVELLE RÉVISION: Le tableau de l'allocation de main-d'œuvre a été révisé en raison de l'application incorrecte des ETP aux groupes respectifs, ce qui a entraîné l'omission de temps pour les essais routiers, les alignements ou le temps requis pour peindre les essieux au besoin. De plus, certaines étapes ont été ajoutées aux instructions de travail, tandis que d'autres ont été réorganisées pour en améliorer la clarté.

Si vous avez des questions ou avez besoin de plus d'informations, contactez le service des campagnes de garantie en soumettant une demande via le lien WSC sur DTNAPortal.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.