

Safety Recall 23KWE: T280, T380, T480 Driveline Flange Fasteners

[Edit](#) [Clone](#)

Number

23KWE / 23V504 / 2023-437

Supplier

Kenworth Truck Company

Description

Safety Recall 23KWE: T280, T380, T480 Driveline Flange Fasteners

Date

8/7/2023

What's New

Safety Recall: Interim Notification

Certain vehicles built with TX-8 transmissions with flange mounted yokes may not have a locking feature installed on fastener threads. This may allow the driveline fasteners to become loose. Parts and repair steps are not yet available. This bulletin will be updated when a repair path is determined.

Introduction

A locking feature may not be installed on flange mounted yoke fasteners. This may allow the driveline fasteners to become loose, increasing the risk of a crash or injury.

Driver(s) may feel vibration while driving at certain speeds.

Situation

25 (22 US and 3 CAN) Model Year 2023-2024 T280, T380 and T480 chassis built from 03/16/2022 through

05/08/2023 that have TX-8 transmissions with flange mounted yokes.

Resolution

Safety Recall - Interim Notification

This bulletin will be updated when repair parts and procedure are available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[Chassis List](#)

Authored by: JK / JB3