

Reference Number: GCUS-3-3231

REVISION: N232419341-01 – Safety Recall - Ignition Coil Pack Fuse - Revised Service Procedure

GENERAL MOTORS

DCS6878

URGENT - DISTRIBUTE IMMEDIATELY

Date: May 1, 2024

Subject: REVISION: N232419341-01 – Safety Recall

Ignition Coil Pack Fuse

Revised Service Procedure

Models: 2023 Chevrolet 3500/4500 Low Cab Forward

2024 Chevrolet 3500 HG/4500 HG Low Cab Forward

2024 Chevrolet 5500 HG/5500 XG Low Cab Forward

Equipped with 6.6L Gasoline Engine (RPO L8T)

This bulletin is being revised to update the Service Procedure. Please discard all previous copies of N232419341.

END OF MESSAGE