



88A REPAIR PROCEDURE FOR 22MY MP (JEEP COMPASS)

After completing the 88A recall repair procedure on 2022 (MP) Jeep Compass vehicles, some vehicles may experience an issue with the A/C function. A new wiTECH routine will be included in the 88A procedure soon to prevent this. In the interim, please do not order new A/C parts to attempt to fix the issue. It is not a hardware issue. To address current vehicles, let the vehicle enter a sleep cycle (3 hour sit) or drive the vehicle for approximately 15 miles. This will reset the parameter and return the A/C function.

If you have any questions on this please don't hesitate to reach out to your Area Manager or Tech Advisor.

