

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Gregory Gunther, Senior Manager, Vehicle Compliance and Analysis, Engineering Services
RE: Recall Campaign Launch Notification Inspect Headlamp Adjustment MY22 A-Class and GLA (177 and 247)	DATE: October 20, 2023

IMPORTANT RECALL CAMPAIGN UPDATE

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis



Recall Campaign Launch Notification			October 20, 2023
Campaign No. :	NHTSA ID	Campaign Desc. :	Inspect Headlamp Adjustment
2023100005	23V662	23P8291012	
<p>This is to notify you of the Recall Campaign Launch to adjust the headlamps on 32 Model Year (“MY”) 2022 A-Class and GLA (177 and 247 platform) vehicles. The recall campaign will be visible on the www.NHTSA.gov website and may generate questions from customers. Affected VINs will be flagged in VMI as “OPEN” on October 20, 2023.</p>			
Background			
Issue	Mercedes-Benz AG (“MBAG”), the manufacture of Mercedes-Benz vehicles, has determined that on certain A-Class and GLA (177 and 247 platform) vehicles, the headlamp adjustment might not meet current production specifications. In this case, the headlamps might be adjusted slightly too high and exceed the range specified by FMVSS 108 S.10 by approximately 0.05%. A headlamp adjustment that is outside of specifications has the potential to create glare for oncoming traffic, which could increase the risk of a crash.		
What We’re Doing	MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will inspect the headlamp adjustment on the affected vehicles and correct it, if necessary.		
Parts	The remedy is available and can be performed.		
Vehicles Affected			
Vehicle Model Year(s)	2022		
Vehicle Model	A-Class and GLA		
Vehicle Populations			
Total Recall Population	32		
Total Vehicles in Dealer Inventory	0		
<p>Given this notice, it is a violation of Federal law for a dealer to sell or lease any new vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Once the remedy is available, the vehicles will be flagged as “OPEN” and Work Instructions will be available in NetStar VMI and Xentry Portal. Once the repair is complete, the vehicle may be sold or leased.</p> <p>Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. As a matter of normal service process, please check for other repair measures which might be applicable to the vehicle(s).</p> <p>Additionally, given this notice, it is a violation of Federal Law for car rental companies to rent new vehicles covered by this notification until the vehicle has been repaired.</p>			
Next Steps/Notes			
Customer Notification Timeline	Customer letters will be mailed on November 3, 2023.		
AOMS/SOMS	AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.		
Rental Fleet Partners	This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet representative for further information and next steps. For repairs, please contact your preferred MBUSA dealer.		
Customer Reimbursement	Customer reimbursement is not being offered for this campaign.		
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.			



Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2023100005, October 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Models A-Class and GLA (177 and 247 platform)**
Model Year 2022

Inspect Headlamp Adjustment

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain A-Class and GLA (177 and 247 platform) vehicles, the headlamp adjustment might not meet current production specifications. In this case, the headlamps might be adjusted slightly too high and might exceed the range specified by FMVSS 108 S.10 by approximately 0.05%. A headlamp adjustment that is outside of specifications has the potential to create glare for oncoming traffic, which may increase the risk of a crash. An authorized Mercedes-Benz dealer will inspect the headlamp adjustment on the affected vehicles and correct it, if necessary.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 32 vehicles are affected.

Order No. P-RC-2023100005

Recall Campaign Bulletin

Recall Campaign Bulletin



Recall Campaign Bulletin


Recall Campaign Bulletin

Recall Campaign Bulletin

Inspect Headlamp Adjustment


Work Procedure

1. Inspect headlamp adjustment (left and right) and adjust if necessary.
 -  For basic data, Model 247 AP82.10-P-8260AO and AP82.10-P-8263OF.
 -  For basic data, Model 177 AP82.10-P-8263xx and AP82.10-P-8260N.
-

 **Note:** *The following allowable labor operation should be used when submitting a warranty claim for this repair:*

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
82 910 12	12-1883	Inspect headlamp adjustment, adjust if necessary	0.6

 **Note:** *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.*