

MACK TRUCKS RECALL ALERT



Subject: Safety Recall SC0453, Steering Wheel Bolt Not Tightened to Specification
Recall Number: SRA-M453
Date: November 10, 2023
Applicable Markets: U.S. Canada Export

Description

The steering wheel attachment bolt may loosen and could separate from the steering shaft, resulting in a loose or detached steering wheel. If in operation, there could be a loss of control of the vehicle which could result in a crash. **Owners will be notified and instructed to not drive their vehicles until recall repairs have been completed.**

There have been no field reports, warranty claims or customer complaints associated with this issue.

The remedy will be to replace the steering wheel retention bolt and tighten to specification.

Model and Model Years Affected

- Certain 2024 MD6 and MD7 model vehicles manufactured September 19, 2023, through October 05, 2023.

Vehicle Quantities

- 75 vehicles (74 US, 1 Canada)

Dealer Responsibilities

- The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.
- Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal November 10, 2023.
- Owner notification letters will be released on or before December 15, 2023.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.