

[Next Unread Message](#)

[View Message](#)

Sent on	07	12	2024	Expires on	07	19	2024
From	Supply Operations - Campaign						
Subject	2015-2020 Multi Model Connecting Rod Crankshaft Allocation						

In an effort to support more efficient repairs in your dealership, **over the next several days**, American Honda will be making additional allocations of countermeasure bearings to support TLX and MDX for the following recalls:

Service Information Bulletin: 24-001: *Safety Recall: 2016-20 MDX Connecting Rod Bearing*

Service Information Bulletin: 24-002: *Safety Recall: 2015-2020 TLX Connecting Rod Bearing*

PN	DESCRIPTION	PREVIOUS ALLOCATION (DEALER STOCK QTY)	NEW ALLOCATION (JULY)	NEW DEALER STOCK QTY
13211-5J2-305	BRG A, CONNROD	4	4	8
13212-5J2-305	BRG B, CONNROD	60	30	90
13213-5J2-305	BRG C, CONNROD	120	30	150
13214-5J2-305	BRG D, CONNROD	60	30	90
13215-5J2-305	BRG E, CONNROD	4	4	8
13321-5J6-A01	BRG A, MAIN UPR	1	3	4
13322-5J6-A01	BRG B, MAIN UPR	4	2	6
13323-5J6-A01	BRG C, MAIN UPR	10	5	15
13324-5J6-A01	BRG D, MAIN UPR	3	5	8
13325-5J6-A01	BRG E, MAIN UPR	1	3	4
13341-R9P-A01	BRG A, MAIN LWR	1	1	2
13342-R9P-A01	BRG B, MAIN LWR	4	0	4
13343-R9P-A01	BRG C, MAIN LWR	10	5	15
13344-R9P-A01	BRG D, MAIN LWR	3	7	10
13345-R9P-A01	BRG E, MAIN LWR	1	3	4

Please continue to follow the repair bulletin instructions provided in the following bulletins: 24-001 and 24-002.

These allocations of parts will be replenished upon an approved repair through the Bearing Inspection Inquiry, allowing your dealership to have parts in stock for current and future repairs.

DEALERS WILL NOT BE ABLE TO ORDER THESE PARTS THROUGH IN.

American Honda kindly requests that you do not return or cancel these orders as you will be able to use these parts to complete crankshaft repairs. These orders will be issued with an order reference number beginning with “**SCB**”.

Due to low inventory, these parts will continue to be controlled and allocated based on repairs at your dealership. The connecting rod bearings and any other necessary parts for the repair will be allocated/replenished based on repair approval via Bearing Inspection Inquiry.