News Channel Update | Vans Customer Service and Parts

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Senior Manager, Regulations and Certifications
Re: Initial Recall Campaign Notification Model Sprinter Model Years 2019-2023 Check Partition Wall Bolts	DATE: January, 2024



IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 770.705.0600



Campaign No. :	Campaign Desc. :	Chack Partition Wall Polts	
2023120017	PDGTREWAN	Check Partition Wall Bolts	
This is to notify you of a Pending Recall Campaign to check partition wall bolts on approximately 334 MY 2019-2023 Mercedes-Benz Sprinter Vans. The recall campaign will be visible on the <u>www.safercar.gov</u> website and may generate questions from customers. All affected VINs will be flagged as "PENDING" in VMI and cannot be sold.			
Background			
Issue	Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz Sprinter Vans, has determined that on certain Sprinter (907 platform) vehicles, the bolted connection of the partition wall might not meet specifications. In this case, a deformation of the partition wall under load could be possible. In addition, an influence on the load securing function cannot be ruled out, which could increase the risk of injury in the event of a crash.		
What We're Doing	MBUSA is conducting a voluntary recall. An authorized Mercedes-Benz dealerships will check the partition wall bolts on the affected vehicles and rework them, if necessary.		
Parts	Parts are not yet available.		
Vehicles Affected			
Vehicle Model Year(s)	2019-2023		
Vehicle Model	Sprinter		
Vehicle Populations			
Population	334		
Dealer Inventory	0		
Given this notice, it is <u>a violation of Federal law</u> for a dealer to sell or lease any <u>new</u> vehicles in dealer inventory covered by this notification until the vehicle has been repaired. Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired. Additionally, given this notice, it is <u>a violation of Federal Law</u> for rental companies to rent new vehicles covered by this notification			
until the vehicle has been repaired.			
Next Steps/Notes			
Customer Notification T	imeline An owner notific	ation letter to be mailed in February, 2024.	
AOMS/SOMS	notice to your de		
Rental Fleet Partners	fleet representat contact your pref	fect vehicles in your fleet. Please contact your respective MBUSA ive for further information and next steps. For repairs, please ferred MBUSA dealer.	
While we regret any inconvenience this may cause, we are determined to maintain a high level of vehicle quality and customer satisfaction.			

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 770.705.0600

