

January 2024

To: All Old Dominion Brush Company LLC-affiliated Dealers

Subject: **Notification of Safety Recall and Recall Remedy Instructions for 23V-892**
Certain Old Dominion Brush Company LLC (“ODB”) DLC debris collection vehicles
manufactured in 2021 – 2023
Dump Body Hoist

REASON FOR THIS SAFETY RECALL:

On December 22, 2023, Alamo Group Inc., filed a Defect Information Report with the National Highway Traffic Safety Administration (NHTSA) informing the agency that in DCL vehicles manufactured by ODB, that when the retraction of the hoist that raises and lowers the dump body is blocked or stalled, pressure builds on the hoist and the bolt connecting the rod and the yoke on the hoist assembly can shear, causing the hoist to fail. A hoist failing could cause a dump body to fall and forcefully impact with the chassis, increasing the risk of injury to those in or near the vehicle.

AFFECTED VEHICLES:

Make and Model	Number of vehicles	Production Period
ODB: DCL1000SE25, DCL800SM30, DCL800SM25, DCL800SM20, DCL800TM30, DCL800TM25, DCL800TM20, and DCL750	195	September 1, 2021 – December 7, 2023

REMEDY:

Remedy parts are available now. Dealers will install a pressure relief valve and higher grade bolt in the hoist assembly which will allow for the pressure to bypass the hoist and not allow pressure to build up. This service must be performed on all affected vehicles **at no charge** to the vehicle owner. Attached please find the service procedure for completing this repair. The repair takes about 2 hours to complete.

REIMBURSEMENT:

Alamo Group will reimburse dealers for performing this remedy.

OWNER LETTER MAILING DATE:

Alamo Group will notify owners of this safety recall by letter mailed on or before February 20, 2024.

CUSTOMER CONTACTS:

Dealers should repair any ODB DCL vehicle covered by this safety recall that arrives at their dealerships, whether or not the owner has received a safety recall letter. The ODB Warranty Department (at 804-887-4541), is available to support you in executing a customer-friendly process for remedying these vehicles.

NEW VEHICLES IN DEALER INVENTORY:

Dealers may have covered ODB DCL vehicles in their inventory. **It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment**

(including a tire) covered by this notification under a sale or lease until the defect is remedied.

Violation of this requirement by a dealer could result in a civil penalty against the dealer. Accordingly, you must remedy any covered ODB DCL vehicles in your new vehicle inventory before delivery.

In addition, we request that you remedy before delivery into commerce under a sale or lease any covered pre-owned ODB DCL vehicles in your inventory.

QUESTIONS & ASSISTANCE:

For questions and assistance, including help in identifying whether any vehicles in your inventory are covered by this safety recall, please contact ODB Warranty Department (at 804-887-4541).

Thank you for your attention to this important matter.

Sincerely,

A handwritten signature in black ink, appearing to read 'T. Stumph', enclosed in a thin black rectangular border.

Tim Stumph
President
Old Dominion Brush Company LLC

Attachment: Service Procedure