



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 23E-055
Cummins Campaign #C2717

September 13, 2023



[Redacted]

L9 engine(s) eligible for Cummins Campaign # C2717

Engine Serial Number	Model	Vehicle Identification Number (VIN)
99058788	548	2NP8LJ0X8RM60 [Redacted]



***** IMPORTANT SAFETY RECALL *****
NHTSA Recall No. 23E-055
Cummins Campaign #C2717

September 13, 2023

Dear Cummins Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in certain L9 engines that were manufactured between November 22, 2022, and February 28, 2023

This notice applies to your L9 engine(s) listed in the enclosed engine table.

WHY IS A RECALL BEING CONDUCTED?

The remote fuel filter hoses installed on some of the subject engines may have been damaged during engine production, possibly resulting in a fuel hose that develops leaks or becomes disconnected. A fuel hose that becomes disconnected will result in an engine stall, increasing the risk of a crash. A fuel leak in the presence of an ignition source may increase the risk of a fire.

WHAT ARE WE DOING ABOUT THE PROBLEM?

Cummins has released field Safety Campaign #C2717 "L9 Remote Mount Stage 2 Fuel Hose Safety Campaign" to correct this condition by replacing the two subject fuel hoses with hoses having improved connector crimps.

Repair parts are currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge (parts and labor) and most applications will require approximately 1 hour to complete.

WHAT SHOULD YOU DO?

Contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete this repair.

In the meantime, however, Cummins advises you to periodically check the remote fuel filter hoses for signs of leaking, and immediately seek repairs if leaks are identified.



If you have not registered your Cummins product, please complete the enclosed registration card or register your product at <https://prodreg.cummins.com/prodreg/#/webform/contactInfo>.

If you are no longer the owner, please forward this notice to the new owner or provide the new owner's contact information to Cummins at cummins.campaign.administration@cummins.com so that we can notify them of this recall.

If you previously paid to have this recall performed on your vehicle, you may be eligible for reimbursement. Please contact Cummins Care at the number below for more information.

Federal law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. Also, it is a violation of Federal law for a dealer to deliver new vehicle or equipment covered by this recall notice under a sale or lease until the defect has been remedied.

WHO SHOULD YOU CONTACT IF YOU HAVE FURTHER QUESTIONS OR CONCERNS?

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800-CUMMINS (1-800-286-6467) or visit our website at care.cummins.com.

If you have a complaint relative to this recall, you may report it to the following:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Cummins is taking this action in the interest of safety and satisfaction with our products. We apologize for any inconvenience and thank you for your attention to this matter.

Sincerely,

Campaign Administrator
Cummins Inc.