



# Thor Motor Coach Recall Repair Instructions

Recall #	<b>23v-068 &amp; 2023-050</b>		
Description/Title:	<b>Rize/Scope 18M awnings</b>		
Affected Product Line(s):	<b>Certain model year</b> 2021 – 2023 Scope 2021 – 2023 Rize		
Service Campaign #	<b>RC000289</b>	Released Date:	<b>2/14/2023</b>
Repair Code:	<b>Repair: TMCRC10110V</b>	Document Date:	<b>3/22/2023</b>
Time Allowed:	<b>Repair: 0.5</b>	Document Revision:	<b>A</b>

## **Issue:**

It has been discovered that on certain model 2021 – 2023 Scope/Rize motorhomes that the awning may drift out during transit.

## **Tools:**

Wire cutters  
Wire strippers  
9/16” wrench  
Screwdriver

## **Parts:**

0543422 - RECALL RC000289 # 23v-068 & 2023-050 SCOPE/RIZE 18M AWNING HARNESS

