



**SIB 65 09 23**  
**RECALL 23V-079: DRIVER'S FRONT AIR BAG**

2023-02-27

<input checked="" type="checkbox"/>	THIS REPAIR IS MOBILE FRIENDLY
-------------------------------------	--------------------------------

This Service Information Bulletin (Revision 2) replaces SI B65 09 23 **dated February 2023.**

**What's New:**

- Recall number added to SIB title
- Recall Notice and Q&A Attachments updated with the recall number
- Cause, Correction, Procedure, Parts, Parts Retention and Return & Claim information added

**MODEL**

E-Series	Model Description	Production Date
I20	iX Sports Activity Vehicle	October 14, 2021 – February 1, 2023

**AFFECTED VEHICLES**

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. You can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

**SITUATION**

BMW AG has issued a Delivery Stop (effective February 3, 2023) on certain Model Year 2022 – 2023 BMW iX SAV vehicles that were produced between October 14, 2021 and February 1, 2023.

As of February 8, 2023, this delivery stop has been upgraded to a Safety Recall.

The driver air bag may not have been produced according to specifications by the supplier. In rare cases, the air bag may not deploy exactly as intended in a crash, which could increase the risk of injury.

The Recall Notice and Q&A have been attached for further information.

**CAUSE**

The driver air bag (in the steering wheel) may not have been produced according to specifications by the supplier.

**CORRECTION**

Replace the driver's air bag.

**PROCEDURE**

**Note: Special tool usage and A-pillar paint finish protection instructions are included in the “Moving the hood to the service position” repair instruction.** Follow repair instruction to install adhesive tape prior to moving the hood to the service position to avoid paint damage.

**Important Warning for Working on the High-Voltage (HV) systems on BMW Group vehicles:**

**Only properly trained personnel, who passed all applicable HV Technical Training Courses, should perform repairs which require disconnecting, or removal of High Voltage battery components on any Hybrid or Electric Vehicle. Work performed on High Voltage systems by unqualified persons may result in severe injury or damage to the vehicle. Additional safety information is found in Repair Instruction 61 00... “Observe safety instructions when handling electric vehicles”.**

**Additional Information:**

**Scheduled Maintenance, or Quality Certification 1 (Pre-Delivery Inspection) on Electric or Hybrid vehicles does not require HV technical training.**

**Prior to disconnecting, or the removal of any HV component, the HV system needs to be disabled and secured (by means of the HV Disconnect Switch) by a properly trained technician, who has a minimum HV Qualification level after completing the Technical Training Course ST1824 (Alternative Drive Part 1). Once the vehicle's HV system is disabled (the "Blitz" - lightning bolt icon displayed in instrument cluster, see below), a technician without HV Certification may remove a HV component (e.g., EH Heater, EKK Compressor, EME Control Unit, et.), except for the High Voltage Battery.**

Replace the driver's airbag module in accordance with repair instructions **32 34 030** Removing and installing air bag unit.

The serial number of the removed air bag AND the new air bag must both be stated on the repair order and in the comments section of the warranty claim.

**PARTS INFORMATION**

**Use and invoice the part number below.**

Part Number	Description	Quantity
32 20 9 483 052	Driver's side air bag unit	1
83 19 9 410 979	Yellow plastic adhesive tape (W=50 mm, L=66 m)	As needed

Additionally, other materials and small parts that are not specified above, such as fluids, lubricants, one-time use screws, nuts, and seals, which must be replaced or installed according to the ISTA repair instructions/ETK, must be selected from the Electronic Parts Catalog, or other approved BMW resources, according to the respective vehicle type. Invoiced these items separately under the Defect Code below.

**Part Retention and Return**

The parts replaced to perform and submit for this Recall repair procedure are the property of BMW NA.

Your center is responsible for the proper identification, storage and documentation of these parts. They must be held in a secure retention area until notification of claim payment is made by BMW NA

**CLAIM INFORMATION**

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below and the part number listed above.

<b>Defect Code:</b>	<b>0032400300</b>	---
---------------------	-------------------	-----

**Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop**

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 73 851	Replacing the driver's air bag module	4 FRU

Or:

**The vehicle arrives at your center and this Recall shows open (No other Main work will be performed or claimed during this workshop visit)**

Work Pkg	Labor	Description (Main work)	Labor Allowance
----------	-------	-------------------------	-----------------

Copyright ©2023 BMW of North America, Inc.

	<b>Operation</b>		
# 2	00 73 265	Replacing the driver's air bag module	6 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

### Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B65 09 23 WP 1), unless otherwise required by State law.

### Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

Based on the issue and the age of the Affected Vehicles being addressed by this Safety Recall Campaign, a reimbursement request for a qualifying prior customer-pay repair is not likely.

However, if you do receive a reimbursement request from a customer for a prior repair that may qualify, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will review and respond to your inquiry accordingly.

### FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

### Supporting Materials

[picture\\_as\\_pdf B650923 Recall Notice.pdf](#)

[picture\\_as\\_pdf B650923\\_23V-079-U11-I20-DriverAirBag-FAQ-\(08Feb2023\).pdf](#)



## **SAFETY RECALL NOTICE**

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 23V-079: Driver's Front Air Bag – B65 09 23

BMW AG has issued a Delivery Stop (effective February 3, 2023) on certain Model Year 2022 – 2023 BMW iX SAV vehicles that were produced between October 14, 2021 and February 1, 2023.

As of February 8, 2023, this delivery stop has been upgraded to a Safety Recall.

**Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.**

**Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.**

**Please follow any special instructions that we provide to you for the return or disposition of recall parts.**

We appreciate all your assistance with this Recall.

**Safety Recall**  
**23V-079**  
**Driver Air Bag**  
**Model Year 2022-2023**  
**BMW X1 SAV, iX**  
**Issue Date: 02/08/2023**

- Q1. Which BMW Group models in the US are potentially affected by this Safety Recall?**  
Model Year 2022-2023 BMW X1 SAV and iX models in the US are potentially affected.
- Q2. What is the specific issue?**  
The driver air bag may not have been produced according to specifications by the supplier. In rare cases, the air bag may not deploy exactly as intended in a crash, which could increase the risk of injury.
- Q3. Why are other models / vehicles not included in this Safety Recall?**  
Other models / vehicles have driver air bags that were produced to specifications by the supplier.
- Q4. Can I continue to drive my vehicle?**  
Yes. However, when you are notified by BMW of this Safety Recall, please contact an authorized BMW center to schedule an appointment as soon as possible. For the latest updates to this Safety Recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall). **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**
- Q5. How did BMW Group become aware of the issue?**  
BMW Group became aware of the issue through its quality control procedures.
- Q6. How will I be informed of this Safety Recall?**  
Owners of potentially affected vehicles will be notified via First Class mail and requested to schedule an appointment with an authorized BMW center to have the remedy performed. Owners can locate their nearest authorized BMW center at [bmwusa.com/dealer](https://www.bmwusa.com/dealer).
- To ensure BMW has the most up-to-date contact and vehicle information, owners should register their vehicle at [www.bmwusa.com/myBMW](https://www.bmwusa.com/myBMW). Registration is free and will give them access to other information specific for their BMW vehicle. Alternatively, owners can visit [bmwusa.com/recall](https://www.bmwusa.com/recall) and click on “**Manage recall notices and contact information**”.
- Q7. How will my vehicle be remedied?**  
Potentially affected vehicles will have the driver air bag replaced for free and should take about one hour.
- Q8. Do I have to wait for BMW to contact me to have the remedy performed?**  
Yes. We are in the process of implementing this Safety Recall to ensure that the necessary parts, tools, and procedures are available. For the latest updates to this recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall).



SIB 65 10 23

2023-02-27

**RECALL 23V-079: DRIVER'S FRONT AIR BAG**

This Service Information Bulletin (Revision 2) replaces SI B65 10 23 **dated February 2023.**

**What's New:**

- Recall number added to SIB title
- Recall Notice and Q&A Attachments updated with the recall number
- Cause, Correction, Procedure, Parts, Parts Retention and Return & Claim information added

**MODEL**

<b>E-Series</b>	<b>Model Description</b>	<b>Production Date</b>
U11	X1 Sports Activity Vehicle	August 2, 2022 – February 1, 2023

**AFFECTED VEHICLES**

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. You can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

**SITUATION**

BMW AG has issued a Delivery Stop (effective February 3, 2023) on certain Model Year 2023 BMW X1 SAV vehicles that were produced between August 2, 2022 and February 1, 2023.

As of February 8, 2023, this delivery stop has been upgraded to a Safety Recall.

The driver air bag may not have been produced according to specifications by the supplier. In rare cases, the air bag may not deploy exactly as intended in a crash, which could increase the risk of injury.

The Recall Notice and Q&A have been attached for further information.

**CAUSE**

The driver air bag (located in the steering wheel) may not have been produced according to specifications by the supplier.

**CORRECTION**

Replace the driver's air bag.

**PROCEDURE**

Replace the driver's airbag module in accordance with repair instructions **32 34 030** Removing and installing air bag unit.

The serial number of the removed air bag AND the new air bag must both be stated on the repair order and in the comments section of the warranty claim.

**PARTS INFORMATION**

**Use and invoice the part number below.**

<b>Part Number</b>	<b>Description</b>	<b>Quantity</b>
32 30 9 496 574	Driver's side air bag unit	1

Additionally, other materials and small parts that are not specified above, such as fluids, lubricants, one-time use screws, nuts, and seals, which must be replaced or installed according to the ISTA repair instructions/ETK, must be selected from the Electronic Parts Catalog, or other approved BMW resources, according to the respective vehicle type. Invoiced these items separately under the Defect Code below.

### Part Retention and Return

The parts replaced to perform and submit for this Recall repair procedure are the property of BMW NA.

Your center is responsible for the proper identification, storage and documentation of these parts. They must be held in a secure retention area until notification of claim payment is made by BMW NA

### CLAIM INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below and the part number listed above.

<b>Defect Code:</b>	<b>0032410300</b>	---
---------------------	-------------------	-----

### Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 73 852	Replacing the driver's air bag module	3 FRU

Or:

### The vehicle arrives at your center and this Recall shows open (No other Main work will be performed or claimed during this workshop visit)

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 2	00 73 266	Replacing the driver's air bag module	5 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

### Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B65 10 23 WP 1), unless otherwise required by State law.

### Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

Based on the issue and the age of the Affected Vehicles being addressed by this Safety Recall Campaign, a reimbursement request for a qualifying prior customer-pay repair is not likely.

However, if you do receive a reimbursement request from a customer for a prior repair that may qualify, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will review and respond to your inquiry accordingly.

### FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS

Copyright ©2023 BMW of North America, Inc.



	Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

Supporting Materials

[picture\\_as\\_pdf B651023\\_23V-079-U11-I20-DriverAirBag-FAQ-\(08Feb2023\).pdf](#)

[picture\\_as\\_pdf B651023 Recall Notice.pdf](#)



## **SAFETY RECALL NOTICE**

To: All Center Operators, Sales Managers, Service Managers, Parts Managers and Warranty Processors

RE: Recall 23V-079: Driver's Front Air Bag – B65 10 23

BMW AG has issued a Delivery Stop (effective February 3, 2023) on certain Model Year 2023 BMW X1 SAV vehicles that were produced between August 2, 2022 and February 1, 2023.

As of February 8, 2023, this delivery stop has been upgraded to a Safety Recall.

**Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that Centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.**

**Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.**

**Please follow any special instructions that we provide to you for the return or disposition of recall parts.**

We appreciate all your assistance with this Recall.

**Safety Recall  
23V-079  
Driver Air Bag  
Model Year 2022-2023  
BMW X1 SAV, iX  
Issue Date: 02/08/2023**

- Q1. Which BMW Group models in the US are potentially affected by this Safety Recall?**  
Model Year 2022-2023 BMW X1 SAV and iX models in the US are potentially affected.
- Q2. What is the specific issue?**  
The driver air bag may not have been produced according to specifications by the supplier. In rare cases, the air bag may not deploy exactly as intended in a crash, which could increase the risk of injury.
- Q3. Why are other models / vehicles not included in this Safety Recall?**  
Other models / vehicles have driver air bags that were produced to specifications by the supplier.
- Q4. Can I continue to drive my vehicle?**  
Yes. However, when you are notified by BMW of this Safety Recall, please contact an authorized BMW center to schedule an appointment as soon as possible. For the latest updates to this Safety Recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall). **If you are not the only driver of this vehicle, please advise all other drivers of this important information.**
- Q5. How did BMW Group become aware of the issue?**  
BMW Group became aware of the issue through its quality control procedures.
- Q6. How will I be informed of this Safety Recall?**  
Owners of potentially affected vehicles will be notified via First Class mail and requested to schedule an appointment with an authorized BMW center to have the remedy performed. Owners can locate their nearest authorized BMW center at [bmwusa.com/dealer](https://www.bmwusa.com/dealer).
- To ensure BMW has the most up-to-date contact and vehicle information, owners should register their vehicle at [www.bmwusa.com/myBMW](https://www.bmwusa.com/myBMW). Registration is free and will give them access to other information specific for their BMW vehicle. Alternatively, owners can visit [bmwusa.com/recall](https://www.bmwusa.com/recall) and click on “**Manage recall notices and contact information**”.
- Q7. How will my vehicle be remedied?**  
Potentially affected vehicles will have the driver air bag replaced for free and should take about one hour.
- Q8. Do I have to wait for BMW to contact me to have the remedy performed?**  
Yes. We are in the process of implementing this Safety Recall to ensure that the necessary parts, tools, and procedures are available. For the latest updates to this recall, please visit [bmwusa.com/recall](https://www.bmwusa.com/recall).