

# Recall Campaign Bulletin



Mercedes-Benz

Campaign No. 2023040004, April 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model CLA (118 platform)**  
**Model Year 2023**

## **Replace Tires**

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that the tires on certain Model Year (“MY”) 2023 CLA (118 platform) vehicles might not meet specifications due to a certain batch of tires having irregularities in the bead area of the tire. Air leaking from the tire or a sudden loss of air pressure cannot be ruled out completely. This might impair the driving stability of the vehicle, which could increase the risk of a crash or injury. In the event of a loss of tire air pressure, the driver might be made aware of the issue by a yellow warning lamp, warning tone and a warning message “Check Tires” or “Please Correct Tire Pressure” in the instrument cluster. An authorized Mercedes-Benz dealership will replace all four tires on the affected vehicles.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 3 vehicles are affected.

Order No. P-RC-2023040004

# Recall Campaign Bulletin

Recall Campaign Bulletin

Recall Campaign Bulletin


Recall Campaign Bulletin

Recall Campaign Bulletin

## Replace all summer tires (x4)

---


### Work Procedure

1. Replace all Michelin summer tires (x4).  
 For basic data, see AR40.10-P-1030MFA.
- 


### Primary Parts Information

Qty.	Part Name	Part Number
4	Michelin summer tires	*

\* The summer tires must be procured via the usual ordering channel, taking into account the approved wheel/tire combinations and tire recommendation according to WIS.


 Small parts such as balance weights, screws/bolts, lock nuts, sealing rings, cable ties, fluids, sealants, etc. are not included in the parts list. The required small parts are taken into account in the budgeting.

---

 **Note:** *The following allowable labor operation should be used when submitting a warranty claim for this repair.*

### Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)
40 922 14	12-1680	Replace tires (4)	2.3

 **Note:** *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.*