


## RECALL 23V286 / 2023-242 REMEDY INSTRUCTIONS

	Make(s): MANY, SEE BELOW Model(s): MANY, SEE BELOW Model Year(s): MANY, SEE BELOW	Repair Code: N/A Allotted Time: N/A Inspection Code: N/A Allotted Time: N/A
	Concern: According to Cummins Onan Recall 23E030: "This fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak."	Photo(s) Required: N/A Prior Authorization Required: N/A Part(s) Kit Number: N/A Part(s) Return: N/A

CERTAIN: 2021 - BYB22RBRWD

CERTAIN: 2022 - SSC2370AFT

CERTAIN: 2023 - NAB20D

CERTAIN: 2021 – 2022 - BYB22CRWD, BYB22DRWD, FRC2381AFT, FRC2381FT, NAB20RB, NAB20RBM, SSC2370FT & SSC2380FT

CERTAIN: 2021 – 2023 - BYB22CAWD, BYB22CFCD, BYB22DAWD, BYB22RBAWD, FRC2371AFT, FRC2371FT

CERTAIN: 2021 – 2024 - NAB20C

FOREST RIVER, INC. IS DIRECTING DEALERS AND OWNERS TO CONTACT CUMMINS DIRECTLY TO HAVE THE GENERATOR(S) REMEDIED.

GENERATORS **MUST** BE REMEDIED BY CUMMINS, OTHERWISE THE WARRANTY WILL BE VOIDED.

PLEASE HAVE THE SERIAL NUMBER OF THE GENERATOR AVAILABLE AND CONTACT CUMMINS AT:

(800) CUMMINS OR (800) 286-6467